

N60200.AR.004113  
NAS CECIL FIELD, FL  
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
REVIEW OF SECOND AND THIRD QUARTER 2004 OPERATIONS AND MAINTENANCE  
REPORTS FOR 103RD STREET/A AVENUE JET FUEL PIPELINE NAS CECIL FIELD FL  
3/15/2005  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



# Department of Environmental Protection

Jeb Bush  
Governor

Twin Towers Building  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

Colleen M. Castille  
Secretary

March 15, 2005

Mr. Gabe Magwood  
Code ES24 (UST RPM)  
Southern Division  
Naval Facilities Engineering Command  
Post Office Box 190010  
North Charleston, South Carolina 29419-9010

RE: Second Quarter 2004 and Third Quarter 2004, Operation and Maintenance Status Reports, April 1, 2004 - June 30, 2004 and July 1, 2004 - September 30, 2004, 103<sup>rd</sup> Street and "A" Avenue, Jet Fuel Transfer Pipeline, Naval Air Station Cecil Field, Jacksonville, Florida


Dear Mr. Magwood:

I have completed my review of the Second Quarter 2004 and Third Quarter 2004, Operation and Maintenance Status Reports, April 1, 2004 - June 30, 2004 and July 1, 2004 - September 30, 2004, 103<sup>rd</sup> Street and "A" Avenue, Jet Fuel Transfer Pipeline, Naval Air Station Cecil Field, dated October 2004 and December 2004 (received October 20, 2004 and January 19, 2005), prepared and submitted by Terraine, Inc. The reports acceptably document the post-active remediation monitoring being conducted pursuant to the Department's April 23, 2003 Post-Active Remediation Monitoring Plan Approval Order (PARMAO). The Department cannot at this time concur with the recommendation to discontinue groundwater sampling and remove the air sparge/soil vapor extraction system from the site. Pursuant to PARMAO, it is required that groundwater contaminant concentrations meet the groundwater cleanup target levels (GCTLs) for the last two sampling events. Because only lead was detected above its GCTL in groundwater during the Second Quarter 2004 monitoring event and no contamination was detected above GCTLs during the Third Quarter 2004 monitoring event, it is required that another groundwater sampling event be conducted. For the next groundwater sampling event, only lead is required to be analyzed for. If lead concentrations in groundwater are below its GCTL, a Site Rehabilitation Completion Report should be prepared and submitted to the Department.

Mr. Gabe Magwood  
March 15, 2005  
Page Two

If I can be of any further assistance with this matter,  
please contact me at (850) 245-8997.

Sincerely,



David P. Grabka, P.G.  
Remedial Project Manager

cc: Mark Davidson, SouthDiv  
Jim Young, Terraine, Inc.  
Doyle Brittain, USEPA Region 4  
Mike Fitzsimmons, FDEP Northeast District

JJC



ESN

