

## **Summary Report**

---

**Repairs to Vehicle Washrack at Building 386  
Solid Waste Management Unit (SWMU) Number 110  
Petroleum Corrective Action Program  
Marine Corps Air Station, El Toro, California**

**4 February 1999**

*Prepared by*  
**Southwest Division, Naval Facilities Engineering Command  
BRAC Operations Office  
1420 Kettner Boulevard, San Diego, CA 92101**

## TABLE OF CONTENTS

<b>Section</b>	<b>Page</b>
<b>1 Introduction</b>	<b>1</b>
<b>2 Field Activities and Previous Investigations</b>	<b>2</b>
<b>3 Conclusions and Recommendations</b>	<b>4</b>
<b>4 References</b>	<b>5</b>

### Figures

- Figure 1. Vicinity Map
- Figure 2. Tentative Reuse Parcel Locations
- Figure 3. Conceptual Site Model

### Appendices

- A Site Photographs and Field Documentation
- B Record Search Documentation

## **Section 1**

### ***Introduction***

The purpose of this Summary Report is to present information pertaining to the repairs to the concrete surface of the vehicle washrack located adjacent to Building 386 at the Marine Corps Air Station (MCAS), El Toro. Petroleum hydrocarbons were identified in the shallow soils beneath the washrack during the Resource Conservation and Recovery Act (RCRA) Facility Assessment (RFA), and the washrack was designated Solid Waste Management Unit (SWMU) Number 110 in the RFA reports. Cracks in the surface of the washrack were also identified, and the RFA reports included the recommendation that the cracks be repaired in order to reduce the migration of residual petroleum hydrocarbons. The Base Realignment and Closure Cleanup Plan also includes this recommendation. The repairs to the cracks in the washrack surface were the primary objectives of this project. This report also includes a brief discussion of the information collected during the RFA and other previous investigations and a recommendation that no further action status be requested for this site.

The Marine Corps Air Station, El Toro, also known as the Station, comprises approximately 4,700 acres and is located in eastern Orange County approximately 45 miles southeast of Los Angeles, California. Building 386 and the adjacent vehicle washrack, SWMU 110, are located in the southwest section of the Station within the Public Works compound near South Marine Way as shown on Figure 1.

SWMU 110 is also located within the boundary of Installation Restoration Program (IRP) Site 24 (Volatile Organic Compound (VOC) Source Area). Chlorinated solvents, including trichloroethylene (TCE), have been detected in the vadose zone and in the ground water beneath IRP Site 24.

The Station is preparing for closure in July 1999 in accordance with the Base Closure and Realignment Act of 1993 (BRAC III). SWMU 110 is located within a 53-acre parcel tentatively identified as a cargo area according to the El Toro Community Reuse Plan, 1997 Working Map (County of Orange, 1997) as shown on Figure 2. The Airport and Open Space Plan, Year 2020, Concept C (County of Orange, August 1998) indicates that SWMU 110 is located within a cargo area.

## **Section 2**

### ***Field Activities and Previous Investigations***

SWMU 110, the vehicle washrack located adjacent to Building 386, was visually inspected by representatives from Southwest Division, Naval Facilities Engineering Command (SWDIV) in July 1998 in order to prepare for the field activities. The washrack is constructed of portland cement concrete and is located on the northeast side of Building 386. The washrack surface area is approximately 3,200 square feet (JEG, 1993), and the surface is sloped toward the drain at the center of the slab. A concrete berm, approximately 3 inches high, surrounds the washrack slab and prevents the flow of water onto the adjacent asphalt pavement parking area. No significant stains were observed on the washrack surface.

#### **2.1 Repairs to Cracks**

Repairs to the cracks in the surface of SWMU 110 were implemented in December 1998 by GEOFON, Incorporated under Navy Contract N68711-97-D-8702, Delivery Order 19. Photographs of the washrack and field notes are provided in Appendix A. Most of the surface cracks were one-half inch to one inch deep.

GEOFON prepared the washrack slab surface by removing dust and vegetation. Surface cracks were filled with a joint sealant. Information pertaining to the sealant is presented in Appendix A.

The sealed cracks will reduce the infiltration of surface waters through the washrack slab and will reduce the potential migration of subsurface residual petroleum hydrocarbons beneath the slab.

## **2.2 Resource Conservation and Recovery Act (RCRA) Facility Assessment (RFA)**

SWMU 110 was inspected and samples were collected during the RFA. The results of the RFA Sampling Visit are published in the *Installation Restoration Program, Final Resource Conservation and Recovery Act Facility Assessment Report for Marine Corps Air Station, El Toro, California* (Jacobs Engineering Group (JEG), 1993).

The RFA Visual Site Inspection of SWMU 110 was conducted in April 1991. Cracks in the surface of the washrack and stains on the washrack surface were documented during the inspection, and the recommendation to conduct a Sampling Visit was presented.

During the Sampling Visit, nine (9) soil samples were collected from four (4) five-foot deep borings through or near the washrack surface. Samples were collected at depths of 2 and 5 feet below ground surface from borings 110H1, 110H2, 110H3, and 110H4. Samples were analyzed by Environmental Protection Agency (EPA) Method 418.1 (Total Recoverable Petroleum Hydrocarbons (TRPH)) and EPA Method 8240 (Volatile Organic Compounds (VOCs)). TRPH was not detected in samples from three of the four borings (110H1, 110H3, and 110H4). TRPH was detected at concentrations from 440 to 680 milligrams per kilogram in boring 110H2 that was located in close proximity to the washrack drain. Benzene was not detected in samples collected from borings 110H1, 110H2, 110H3, or 110H4. Acetone and methylene chloride were reported in some of the samples, however, the results are qualified due to the presence of the analytes in the blanks. Toluene and tetrachloroethylene (PCE) are reported as estimated values (qualified with "J" qualifier) in some of the samples.

Subsurface soils consist primarily of silty sand and sandy silt according to a boring log for a 62-foot deep boring at SWMU 223 which is located approximately 40 feet from the washrack.

Extracts from the RFA documentation are presented in Appendix B.

## **2.3 Remedial Investigation Soil Gas Survey**

During the Phase I Remedial Investigation of IRP Site 24, a soil gas survey was conducted that included the vicinity of Building 386. Samples were collected from depths of 20 feet or less for analysis of Volatile Organic Compounds (VOCs) and Total Petroleum Hydrocarbons (TPH). The results of the survey are published in the *Marine Corps Air Station, El Toro, El Toro, California, Installation Restoration Program, Remedial Investigation/Feasibility Study, Final Soil Gas Survey, Technical Memorandum, Sites 24 and 25* (Jacobs Engineering Group (JEG), 1994).

The nearest sampling points, 24\_SG83 and 24\_SG89, were located within approximately 100 feet of SWMU 110. Samples were collected at a depth of 15 feet from each point, and no petroleum hydrocarbons or volatile organic compounds were detected in the soil gas samples from these points. Results from the Soil Gas Survey are presented in Appendix B.

#### **2.4 Ground Water Conditions**

Ground water conditions have been investigated in the vicinity of SWMU 110 during the Remedial Investigation of IRP Site 24 (the VOC Source Area) and IRP Site 10 (Petroleum Disposal Area). The nearest monitoring well, 10\_DGMW77, is located approximately 150 feet southeast of and upgradient of SWMU 110. The screened interval of well 10\_DGMW77 is from 130 to 170 feet below ground surface. The water level is approximately 104 feet below ground surface, and the gradient is northwest. Water samples collected from well 07\_DGMW77 contained trichloroethylene (TCE) and other chlorinated solvents during sampling activities conducted during the period from 1991 through 1997 (CDM, 1997). The maximum TCE concentration in a water sample from well 07\_DGMW77 was 107 micrograms per liter measured in March 1997. Additional ground water information is presented in Appendix B.

The nearest agricultural production well, TIC-55, is located approximately 2,000 feet north-northwest of SWMU 110.

SWMU 110 is located above the VOC plume in the shallow aquifer at IRP Site 24 as shown in Figure 3, the conceptual site model. The presence of TCE and other volatile organic compounds is believed to be associated with the sources identified in IRP Site 24 rather than with the residual petroleum hydrocarbons located beneath SWMU 110. The ground water conditions in the vicinity of SWMU 110 will be addressed in the Record of Decision for IRP Site 24 and Operable Unit 1.

### **Section 3**

#### **Conclusions and Recommendations**

The following conclusions are based upon existing information from previous field investigations and the recently completed repairs to the washrack surface:

- The surface of the vehicle washrack - SWMU 110 - at Building 386 has been repaired by filling the cracks in accordance with the recommendations of the RFA Report. The repairs to the cracks will reduce the potential for water from the washrack to contact residual petroleum hydrocarbons located beneath the washrack slab and to cause migration of the residual petroleum hydrocarbons to ground water.

- Residual petroleum hydrocarbons, reported as Total Recoverable Petroleum Hydrocarbons, were identified in boring 110H2 at depths of 2 and 5 feet below ground surface at a maximum concentration of 680 milligrams per kilogram. Benzene was not detected at or above laboratory reporting limits. The residual petroleum hydrocarbon release does not appear to be laterally or vertically extensive, and the residual concentrations are not anticipated to pose a significant threat to ground water which is located approximately 100 feet below ground surface.
- SWMU 110 is located within the boundary of IRP Site 24 - the VOC Source Area. The ground water beneath SWMU 110 has been impacted by chlorinated solvents believed to originate from the primary sources identified within IRP Site 24. Ground water conditions beneath SWMU 110 will be addressed during the development of the Records of Decision for IRP Site 24 - the VOC Source Area and for Operable Unit 1 - Regional Groundwater.

Based upon the absence of evidence of a significant release of petroleum hydrocarbons at SWMU 110 and the completion of the repairs to the cracks in the washrack surface, it is recommended that the Station request *no further action* status for this site from the Regional Water Quality Control Board, Santa Ana Region.

## **Section 4**

### **References**

Airborne Systems, Incorporated. 1990. Topographic survey of Marine Corps Air Station, El Toro.

Bechtel National, Incorporated. 1997. Draft Final Phase II Remedial Investigation Report, Operable Unit 2A-Site 24, Marine Corps Air Station, El Toro, California. [Navy Contract N68711-92-D-4670, Contract Task Order 73]

CDM Federal Programs Corporation. 1997. Final Groundwater Monitoring Report, July 1997 Sampling Round, Groundwater Monitoring Program for Marine Corps Air Station, El Toro. October. [Navy Contract N68711-96-D-2029, Delivery Order 5]

County of Orange. 1997. Alternative A, El Toro Community Reuse Plan, 1997 Working Map, Land Uses/Conveyances, Gross Acres. [Prepared by P&D Consultants for the County of Orange, March 1997.]

**County of Orange. 1998. The Airport and Open Space Plan, Year 2020, Concept C. August.**

**GEOFON, Incorporated. 1999. Technical Information Package for washrack repairs – Building 386 (SWMU 110).**

**Jacobs Engineering Group (JEG). 1993. Installation Restoration Program, Final Resource Conservation and Recovery Act Facility Assessment Report for Marine Corps Air Station, El Toro, California. [Navy Contract N68711-89-D-9296, Contract Task Order 193]**

**Jacobs Engineering Group (JEG). 1994. Marine Corps Air Station, El Toro, El Toro, California, Installation Restoration Program, Remedial Investigation/Feasibility Study, Final Soil Gas Survey, Technical Memorandum, Sites 24 and 25. October. [Navy Contract N68711-89-D-9296, Contract Task Order 145]**

**Jacobs Engineering Group (JEG). 1994. Marine Corps Air Station, El Toro: Installation Restoration Program, Phase I Remedial Investigation Technical Memorandum. [Contract N68711-89-D-9296, Contract Task Order 145]**

**Marine Corps Air Station, El Toro. 1998. Base Realignment and Closure (BRAC) Cleanup Plan.**

SOUTHWESTNAVFACENGCOM  
CODE 58ME.LMH  
SAN DIEGO, CA 92101

## Figures





Figure 1.

SOLID WASTE MANAGEMENT UNIT (SWMU)  
NUMBER 110 - VEHICLE WASHRACK

**VICINITY MAP**


MARINE CORPS AIR STATION, EL TORO

LMH FILE 110REUSE.dgn

**EXPLANATION**

**REUSE PRIORITIES**


- H HIGH PRIORITY
- M MEDIUM PRIORITY
- L LOW PRIORITY



SOURCE COUNTY OF ORANGE, 1997

**Figure 2.**  
**SOLID WASTE MANAGEMENT UNIT (SWMU)  
 NUMBER 110 - VEHICLE WASHRACK**  
**TENTATIVE REUSE PARCEL  
 LOCATIONS**  
**MARINE CORPS AIR STATION, EL TORO**

EMR 1110: 110MDD3.dgn DEC 1998



**LEGEND:**

**RECEPTORS:**

-  WORKERS
-  PETROLEUM IMPACTED SOILS

**PATHWAYS:**

-  GROUND WATER

NOTE: DRAWING IS NOT TO SCALE.

**Figure 3.**  
**SOLID WASTE MANAGEMENT UNIT (SWMU)**  
**NUMBER 110 - VEHICLE WASHRACK**  
**CONCEPTUAL SITE MODEL**  
**MARINE CORPS AIR STATION, EL TORO**

SOUTHWESTNAVFACENGCOM  
CODE 5BME.LMH  
SAN DIEGO, CA 92101

## Appendices

SOUTHWESTNAVFACEGCOM  
CODE 58ME.LMH  
SAN DIEGO, CA 92101

## **Appendix A**


### **Site Photographs and Field Documentation**

**Building 386**

**TYPICAL SURFACE  
CRACK**

**Photograph provided by  
GEOFON**

**SWMU 110 –  
VEHICLE  
WASHRACK**




**Building 369**

**TYPICAL SURFACE  
CRACK**

**SWMU 110 -  
VEHICLE  
WASHRACK**


**Photograph provided by  
GEOFON**

**Repairs to Surface of Vehicle Washrack at Building 306 (Solid Waste Management Unit (SWMU) 110) in December 1998.  
Photo provided by ROICC.**



**Repaired Cracks on Surface of  
Vehicle Washrack at Building 386  
(SWMU 110).**

**Photo provided by ROICC.**



CATALOG CUT/SHOP DRAWING TRANSMITTAL AND APPROVAL  
12ND WESTDIV 4255/1 (REV. 9-78)

See instructions on reverse  
No carbon paper is required to complete this form  
No transmittal letter required

Submittal no. \_\_\_\_\_ COC CLAUSE  IS APPLICABLE  IS NOT APPLICABLE

REFERENCES TO USE WHEN COC CLAUSE IS APPLICABLE **PART I - FOR CONTRACTOR USE** REFERENCES TO USE WHEN COC CLAUSE IS NOT APPLICABLE

(A) ROICC/REICC

FROM (Contractor) **GEORON INC.** TO (A) **A ROICC, MCAS ELTORO**

(A) DESIGNER

(B) (Check one)

CONTRACT NO. **N6871-97-D-8702** CONTRACT TITLE **D.O.# 19 / REMOVAL OF USIT, OWS & WASHTRUCK REPAIR, MCAS ELTORO**

(B) APPROVAL

RECORD

THE FOLLOWING ITEM IS SUBMITTED FOR (B) PER SPECIFICATION SECTION NUMBER **SIKAFLEX-1a**

APPROVAL

VERIFICATION (This form shall not be used for forward proposed substitutions)  
IT IS HEREBY CERTIFIED THAT THE  EQUIPMENT  MATERIAL SHOWN AND MARKED IN THIS SUBMITTAL IS THAT PROPOSED TO BE INCORPORATED INTO CONTRACT NUMBER **N6871-97-D-8702 D.O.# 19** IS IN COMPLIANCE WITH THE CONTRACT DRAWINGS AND SPECIFICATIONS, AND CAN BE INSTALLED IN THE ALLOCATED SPACES.  
**Material cut sheet submitted for Washtruck repairs**

(C) PERSON DESIGNATED BY CONTRACTOR AS HAVING AUTHORITY TO SIGN CERTIFICATION

(C) AUTHORIZED CONTRACTOR QUALITY CONTROL REPRESENTATIVE

DESIGNED BY (C) **M. Helein** DATE **11/6/98**

CURSORY REVIEW REQUIRED ON RECORD COPIES - REPLY TO ROICC ONLY IF APPROPRIATE. DETAILED REVIEW REQUIRED ON SUBMITTALS FOR DESIGNER APPROVAL AND MARK EACH COPY AS APPROPRIATE.

**PART II - FOR DESIGNER USE**

(D) DETAILED REVIEW REQUIRED. STAMP AND MARK EACH COPY AS APPROPRIATE

FROM (Designer) \_\_\_\_\_ TO (ROICC/REICC) \_\_\_\_\_

THIS SUBMITTAL HAS BEEN REVIEWED (D). THE FOLLOWING RECOMMENDATION IS MADE:

ENGINEER (Copy to ROICC)

SIGNATURE \_\_\_\_\_ DATE \_\_\_\_\_

(E) CONTRACTOR (Copy to ROICC)

**PART III - FOR ROICC/REICC USE**

FROM (ROICC/REICC) \_\_\_\_\_ TO (E) \_\_\_\_\_

ENCLOSURES ARE RETURNED WITH THE FOLLOWING COMMENTS:  
  
**APPROVED**  
**SUBJECT TO CONTRACT REQUIREMENTS**

SIGNATURE **Scott Kuhn** DATE **25 Nov 98**

ISO 9000

JIKa

## One part polyurethane, elastomeric sealant/adhesive

### DESCRIPTION

SikaMax-12 is a premium-grade, high-performance, moisture-cured, 1-component, polyurethane-based, non-elastomeric sealant. Meets Federal specification TT-S-00230C, Type II, Class A. Meets ASTM C-920, Type S, Grade NS, Class 25; Canadian Standard 19-GP-16A, Type II.

### WHERE TO USE

- ▲ Designed for all types of joints where maximum depth of sealant will not exceed 1/4 in.
- ▲ Excellent for small joints and joints... windows, doorframes, reglets, flashing, and many construction adhesive applications.
- ▲ Suitable for vertical and horizontal joints; readily placeable at 40 F.
- ▲ Has many applications as an elastic adhesive between materials with dissimilar coefficients of expansion.

### ADVANTAGES

- ▲ Eliminates time, effort, and equipment for mixing, filling cartridges, pre-heating or thawing, and cleaning of equipment.
- ▲ High elasticity - cures to a tough, durable, flexible consistency with exceptional cut and tear-resistance.
- ▲ Stress relaxation.
- ▲ Excellent adhesion - bonds to most construction materials without a primer.
- ▲ Excellent resistance to aging, weathering.
- ▲ Proven in tough climates around the world.
- ▲ USDA-approved.
- ▲ Odorless, non-staining
- ▲ Paintable with water-, oil- and rubber-based paints.
- ▲ Jet fuel resistant.
- ▲ NSF and EPA-approved for potable-water contact. Compatibility tests are recommended.
- ▲ Urethane-based; suggested by EPA for radon reduction.
- ▲ Capable of  $\pm 25\%$  joint movement

### COVERAGE

- ▲ 10.3 fl. oz. cartridge seals 12.4 linear ft. of 1/4 x 1/4 in. joint.
- ▲ 20 fl. oz. uni-pec sausage seals 24 linear ft. of 1/4 x 1/4 in. joint.

### PACKAGING

- ▲ Disposable 10.3 fl. oz., moisture-proof cartridges, 24/case; and uni-pec sausages, 20 fl. oz., 20/carton.

<b>SHelf LIFE</b>	10.3 fl. oz. cartridges 20 fl. oz. uni-pec sausages	12 months 12 months
<b>STORAgE CONDITIONS</b>	Store at 40-85F (4-35C). Condition material to 65-75F before using.	
<b>COLOrS</b>	White, colonial white, aluminum gray, limestone, black, dark bronze, capitol tan. Special architectural colors on request.	
<b>APPLICATIOn TEMPERATURe</b>	40 to 100F. Sealant should be installed when joint is at midrange of its anticipated movement.	
<b>SERVICERAnGE</b>	-40 to 170F	
<b>CURInG RAtE</b>	Tack-free Time Tack-free to touch Final cure	6 to 8 hours (TT-S-00230C) 3 hours 5 to 8 days
<b>RECOVERY (ASTM C719)</b>	>90%	
<b>SHORe A HARdNESS (ASTM D-2240)</b>	21 day 40 $\pm$ 5	
<b>TENSILE PROPERTIES (ASTM D-412)</b>	21 day Tensile Stress Elongation at Break Modulus of Elasticity	140 psi (.96 MPa) 700% 40 psi (.275 MPa) 60 psi (.413 MPa) 80 psi (.551 MPa) 50% 100%
<b>LAP-SHEAR STRENGTH (ASTM D-1002), modified, glass substrate 21 day</b>	50F 73F 122F	120 psi (.827 MPa) 125 psi (.862 MPa) 125 psi (.862 MPa)
<b>ADHESION IN PEEL (TT-S-00230C)</b>	Substrate Aluminum Glass Concrete	Peel Strength 25 lb 20 lb 20 lb
<b>WEATHERING RESISTANCE</b>	Excellent	
<b>CHEMICAL RESISTANCE</b>	Good resistance to water, diluted acids, and diluted alkalis. Consult Technical Service for specific data.	
<b>RADON REDUCTION</b>	Approximately 97% reduction in radon. Independent laboratory evaluation. Actual results available upon request. Consult Technical Service.	

## HOW TO USE

### SURFACE PREPARATION

Clean all surfaces. Joint walls must be sound, clean, dry, frost-free, and free of oil and grease. Curing compound residues and any other foreign matter must be thoroughly removed. Install bond breaker tape or backer rod to prevent bond at base of joint.

### PRIMING

Priming is not usually necessary. Most substrates only require priming if testing indicates a need or where sealant will be subjected to water immersion after cure. Consult Sikaflex Primer Technical Data Sheet or Technical Service for additional information on priming.

### APPLICATION

Recommended application temperatures: 40-100 F. For cold weather application, condition units at approximately 70 F; remove prior to using.

For best performance, Sikaflex-1a should be gunned into joint when joint slot is at mid-point of its designed expansion and contraction.

Place nozzle of gun into bottom of the joint and fill entire joint. Keep the nozzle in the sealant, continue on with a steady flow of sealant preceding the nozzle to avoid air entrapment.

Avoid overlapping of sealant to eliminate entrapment of air. Tools as required. Joint dimension should allow for 1/4 inch minimum and 1/2 inch maximum thickness for sealant. Proper design is 2:1 width to depth ratio.

For use in horizontal joints in traffic areas, the absolute minimum depth of the sealant is 1/2 in. and closed cell backer rod is recommended. Tool as necessary, dry or with clean water.

### LIMITATIONS

- ▲ Allow 1-week cure at standard conditions when using Sikaflex-1a in total water immersion situations and prior to painting.
- ▲ When overcoating with water, oil and rubber based paints, compatibility and adhesion testing is essential.
- ▲ Avoid exposure to high levels of chlorine. (Maximum continuous level is 3ppm of chlorine.)
- ▲ Maximum depth of sealant must not exceed 1/2 in.; minimum depth is 1/4 in.
- ▲ Maximum expansion and contraction should not exceed 25% of average joint width.
- ▲ Do not cure in the presence of curing silicone sealants.
- ▲ Avoid contact with alcohol and other solvent cleaners during cure.
- ▲ Do not apply when moisture-vapor-transmission condition exists from the substrate as this can cause bubbling within the sealant.
- ▲ Use opened cartridges and uni-pac sausages the same day.
- ▲ When applying sealant, avoid air-entrapment.
- ▲ Since system is moisture-cured, permit sufficient exposure to air.
- ▲ White color tends to yellow slightly when exposed to ultra-violet rays.
- ▲ The ultimate performance of Sikaflex-1a depends on good joint design and proper application with joint surfaces properly prepared.
- ▲ Minimum depth of sealant in horizontal joints subject to traffic is 1/2 in.
- ▲ Do not tool with detergent or soap solutions.

## CAUTION

### COMBUSTIBLE

Keep away from open flames and hot heat. Contains xylene; avoid breathing vapors. Use with adequate ventilation.

### IRRITANT

Avoid skin and eye contact. Use of NIOSH MSHA approved organic vapor respirator, safety goggles, and chemical-resistant gloves recommended. Remove contaminated clothing and shoes.

### FIRST AID

In case of skin contact, wash thorough with soap and water. For eye contact flush immediately with plenty of water for at least 15 minutes; contact physician. Wash clothing before re-use. Discard contaminated shoes.

### CLEAN UP

Uncured material can be removed with approved solvent. Cured material can only be removed mechanically. For spillage, collect, absorb, and dispose of it accordance with current, applicable to cal, state, and federal regulations.

Product Code 431 Sika and Sikaflex are registered trademarks. Made in USA. Printed in USA January, 1987

**KEEP CONTAINER TIGHTLY CLOSED  
NOT FOR INTERNAL CONSUMPTION**

**KEEP OUT OF REACH OF CHILDREN  
FOR INDUSTRIAL USE ONLY**

**CONSULT MATERIAL SAFETY DATA SHEET FOR MORE INFORMATION**

SIKA WARRANTS ITS PRODUCTS TO BE FREE OF MANUFACTURING DEFECTS AND THAT THEY WILL MEET SIKAS QUALITY CONTROL PUBLISHED PHYSICAL PROPERTIES WHEN APPLIED IN ACCORDANCE WITH SIKAS INSTRUCTIONS AND TESTED IN ACCORDANCE WITH ASTM AND SIKAS STANDARDS. THERE ARE NO OTHER WARRANTIES BY SIKAS OF ANY NATURE, WHETHER WRITTEN OR IMPLIED, INCLUDING ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE IN CONNECTION WITH THE PRODUCT. SIKAS CORPORATION SHALL NOT BE LIABLE FOR DAMAGES OF ANY SORT, INCLUDING REMOTE OR CONSEQUENTIAL DAMAGES, RESULTING FROM ANY CLAIMED BREACH OF ANY WARRANTY, WHETHER WRITTEN OR IMPLIED, INCLUDING ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR FROM ANY OTHER CAUSE WHATSOEVER. SIKAS SHALL ALSO NOT BE RESPONSIBLE FOR USE OF THIS PRODUCT IN A MANNER TO VIOLATE OR INFRINGE ON ANY PATENT RIGHT BY OTHERS.



**1-800-833-SIKA NATIONWIDE**

**Regional Information and Sales Centers**

*For the location of your nearest Sika sales office, contact your regional center*

**USA Headquarters**  
201 Polio Avenue  
Lyndhurst, NJ 07071  
Phone: 201-633-8800  
Fax: 201-633-8225

**Eastern Region**  
14 Summit Place  
Suite 201  
Branford, CT 06405  
Phone: 203-488-7705  
Fax: 203-488-7790

**Central Region**  
2190 Gladstone Court  
Suite A  
Glandale Heights, IL 60139  
Phone: 630-924-7900  
Fax: 630-924-8508

**Western Region**  
12787 East Imperial Hwy.  
Santa Fe Springs, CA 90670  
Phone: 562-941-0231  
Fax: 562-941-4762

SOUTHWESTNAVFACENGCOM  
CODE 5BME.LMH  
SAN DIEGO, CA 92101

## **Appendix B**

### **Record Search Documentation**

**RCRA Facility Assessment (RFA) Sample Locations, Other RFA Documentation,  
and Soil Gas Data (JEG)**

**Ground Water Conditions (CDM)**

**BRAC Cleanup Plan Extracts (U.S. Marine Corps Air Station, El Toro)**

**MARINE CORPS AIR STATION EL TORO  
EL TORO, CALIFORNIA  
INSTALLATION RESTORATION PROGRAM  
FINAL RESOURCE CONSERVATION  
AND RECOVERY ACT (RCRA)  
FACILITY ASSESSMENT REPORT**

**VOLUME I**

**16 July 1993**

**EXTRACTS**

**PREPARED BY:**  
Southwest Division, Naval Facilities  
Engineering Command  
1220 Pacific Highway  
San Diego, California 92132-5190


**THROUGH:**  
CONTRACT #N68711-89-D-9296  
CTO #193  
**DOCUMENT CONTROL NO:**  
CLE-C01-01F193-S2-0001

**WITH:**  
Jacobs Engineering Group Inc.  
3655 Nobel Drive, Suite 200  
San Diego, California 92122

In association with:  
International Technology Corporation  
CH2M HILL

**Table 6-15**  
**Recommendations for SWMUs/AOCs**  
**MCAS El Toro RFA**

SWMU No.	SWMU/AOC Type	Recommendation (FA/NFA)	Description of Further Action	Rationale for Further Action
84	Oil/Water Separator		Leak test/inspection of separator	Moderate petroleum hydrocarbon contamination at 10-foot dept
88	Drum Storage Area		Shallow soil borings	Potential for PCBs in shallow soil
90	Former Sewage Treatment Plant Sit	NFA	--	--
91	Underground Storage Tank	NFA	--	--
92	Underground Storage Tank	NFA	--	--
95	Engine Test Cell	NFA	--	--
98	Vehicle Wash Rack	NFA	--	--
99	Drum Storage Area	NFA	--	--
100	TCE Degreaser	NFA	--	--
101	Oil/Water Separator	NFA	--	--
102	Underground Storage Tank	NFA	--	--
107	Hazardous Waste Storage Area	NFA	--	--
→ 110	Vehicle Wash Rack		Repair cracks in pavement	Prevent future migration of petroleum hydrocarbons
112	Oil/Water Separator	NFA	--	--
116	Drum Storage Area	NFA	--	--
120	Vehicle Wash Rack	NFA	--	--
124	Hazardous Waste Storage Area	NFA	--	--
125	Hazardous Waste Storage Area	NFA	--	--
129	Underground Storage Tank	NFA	--	--
130	Drum Storage Area	NFA	--	--
131	Engine Test Cell		Shallow soil borings	SVOC above PRG value
132	Oil/Water Separator	NFA	--	--
137	Oil/Water Separator	NFA	--	--
138	Drum Storage Area	NFA	--	--
139	Oil/Water Separator	NFA	--	--
144	Drum Storage Area	NFA	--	--
145	Underground Storage Tank		Additional boring(s)	Petroleum hydrocarbon contamination, unknown extent
147	Drum Storage Area	NFA	--	--
149	Drum Storage Area	NFA	--	--
151	Oil/Water Separator		Leak test/inspection of separator	Moderate petroleum hydrocarbon contamination at 10-foot dept



**Figure 35 Sample Location Map**

**Boring Location and Number:**

- ⊕ 123H4 5' Deep Boring
- ⊙ 123B4 25' Deep Boring
- ▲ 123A4 60' Long, Angle Boring


**Features:**

-  Building
-  Concrete
-  Fence
-  Railroad

**SWMU/AOC Number and Type:**

- 110 - Vehicle Washrack
- 112 - Oil/Water Separator
- 223 - Hazardous Waste Storage Area

**Scale**



**MCAS El Toro  
RCRA Facility Assessment**

**NCAS EL TORO RCRA FACILITY ASSESSMENT - SAMPLING VISIT RESULTS**

SWM/ADC NUMBER	SWM/AOC TYPE (FIGURE)	BORING NUMBER	SAMPLE DEPTH (FEET)	ANALYTICAL TEST RESULTS							RECOMMENDATIONS	
				TPH (mg/kg)	TFH (mg/kg)		VOCs (ug/kg)	SVOCs (ug/kg)	PESTICIDES/PCBs (ug/kg)	METALS (mg/kg)	Action	Rationale
					Gasoline	Diesel						
110	Vehicle Wash Rack (35)	H1	2	ND	NA	NA	Methylene Chloride-4 J *	NA	NA	NA	Repair cracks in pavement.  To prevent future migration of petroleum hydrocarbons.  TPH/TFH < 1000 ppm VOCs < ETM & PRO	
			5	ND	NA	NA	Methylene Chloride-3 J *	NA	NA	NA		
		H2	2	680	NA	NA	Methylene Chloride-4 J *	NA	NA	NA		
			2 (Duplicate)	590	NA	NA	Methylene Chloride-4 J *	NA	NA	NA		
			5	440	NA	NA	Methylene Chloride-20 BJ *	NA	NA	NA		
		H3	2	ND	NA	NA	Methylene Chloride-4 J *	NA	NA	NA		
			5	ND	NA	NA	Methylene Chloride-6 J *	NA	NA	NA		
		H4	2	ND	NA	NA	Methylene Chloride-4 J *	NA	NA	NA		
			5	ND	NA	NA	Methylene Chloride-4 J *	NA	NA	NA		


**Evaluation Form  
SWMU/Area of Concern  
Number 110**

Name: Vehicle Washrack

Location: East of Building 386

Size: 3,200 sq ft

Date of Site Visit: 23 April 91



Period of Operation

Currently active

**Evaluation Form  
SWMU/Area of Concern  
Number 110**

Unit Characteristics

The washrack is located adjacent to the northeastern side of Building 386. It is surrounded by a small unpaved area to the northeast, a concrete parking area to the southeast, and an asphalt paved area on the northwest side of the wash area.

The washrack consists of a concrete wash surface surrounded by a 4-in. concrete berm. The washrack is graded so that all the water flows toward a drain situated in the center of the wash area. The drain leads to oil/water Separator 386-B. The wash pad is badly stained from vehicles being worked on inside the wash area. There are also several cracks in the wash pad where water could possibly leak through to the soil beneath the washrack. A portion of the berm has been removed from the southwestern corner so that vehicles can easily be driven into the wash area. It is unlikely that any water would flow away from this area because it is upgradient from the drain. The southeastern corner of the berm is also badly cracked. There are several stains on the ground outside this corner.

A 500-gallon bowser is stored in the northeastern corner of the washrack. The bowser is used to store waste oil. The bowser is elevated about 3 ft, therefore it is possible for a spill to spread outside the washrack berm. Two drip pans, located next to the bowser, are used to drain oil filters before disposal. There are several dark stains on the washrack's surface next to the bowser and the drip pans.

A hydraulic lift is located next to the bowser. From the stains around the hydraulic lift, it is evident that the hydraulic lift is still used.

Waste Characteristics

Oily waste  
Waste oil  
Hydraulic fluid  
Antifreeze

Possible Migration Pathways

Storm drain system  
Oil/water separator  
Soil

Evidence of Release

Stained wash pad and stained ground outside the washrack

**Evaluation Form  
SWMU/Area of Concern  
Number 110**

**Exposure Potential**

On-Station personnel

**Recommendations**

Based on the stains and cracks in the concrete, this washrack is recommended for a sampling visit.



PROJECT NUMBER LA070022.S0.10	BORING NUMBER 223A-1	SHEET 2 OF 3
----------------------------------	-------------------------	--------------

## SOIL BORING LOG

PROJECT NAVY CLEAN RCRA FACILITY ASSESSMENT LOCATION MCAS-EL TORO  
 ELEVATION \_\_\_\_\_ DRILLING CONTRACTOR BEYLIK DRILLING, INC., LA HABRA, CALIFORNIA  
 DRILLING METHOD AND EQUIPMENT HSA, 3-1/4" ID, 6-1/2" OD, GUS PECH BRAT-22  
 WATER LEVELS \_\_\_\_\_ START 10/23/92 FINISH 10/23/92 LOGGER K. HUCKRIEDE

DEPTH BELOW SURFACE (FT)	SAMPLE			STANDARD PENETRATION TEST RESULTS	SOIL DESCRIPTION SOIL NAME, USCS GROUP SYMBOL, COLOR, MOISTURE CONTENT, RELATIVE DENSITY OR CONSISTENCY, SOIL STRUCTURE, MINERALOGY	COMMENTS DEPTH OF CASING, DRILLING RATE, DRILLING FLUID LOSS TESTS AND INSTRUMENTATION
	INTERVAL	TYPE AND NUMBER	RECOVERY (FT)	6" - 6" - 6" (N)		
40.0	40.0				<b>SILTY SAND (SM)</b> , light brown, dry to moist, dense, fine grained.	Headspace reading 0.6 ppm on OVA.
	42.0	4-MC	1.5	30-37-20-50		
45.0					<b>SANDY SILT (ML)</b> , light brown, dry to moist, hard, fine to medium grained sand, rounded sand particles.	Headspace on OVA similar to background.
50.0	50.0	5-MC	1.7	21-48-59-110		
	52.0				<b>LEAN CLAY WITH SAND (CL)</b> , brown, moist, fine grain size, medium plasticity.	Headspace on OVA similar to background.
60.0	60.0	6-MC		35-44-64-73		
	62.0				Total Depth at 62.0 Feet.	
65.0						

**EXTRACTS**

**MARINE CORPS AIR STATION EL TORO  
EL TORO, CALIFORNIA  
INSTALLATION RESTORATION PROGRAM  
REMEDIAL INVESTIGATION/FEASIBILITY STUDY  
FINAL SOIL GAS SURVEY  
TECHNICAL MEMORANDUM  
SITES 24 AND 25**

**Revision 0**

**PREPARED BY:**  
Southwest Division, Naval Facilities  
Engineering Command  
1320 Pacific Highway  
San Diego, California 92132-8190

**THROUGH:**  
CONTRACT #N68711-89-D-8296  
CTO #145  
DOCUMENT CONTROL NO:  
CLE-C01-01F145-S2-0004

**WITH:**  
Jacobs Engineering Group Inc.  
3633 Nobel Drive, Suite 200  
San Diego, California 92122

In association with:  
International Technology Corporation  
CH2M HILL

*John Dolegowski* 28 Oct '94

Date


John Dolegowski  
CLEAN Project Manager  
CH2M HILL, Inc.

*Michael Bitner*

27 OCT '94

Date

Michael Bitner, R.G.  
CLEAN Technical Reviewer  
CH2M HILL, Inc.



**PLATE 1**  
**SAMPLE LOCATION MAP**

Table C-1  
 Concentrations in Soil Gas  
 MCAS El Toro Soil Gas Survey Technical Memorandum

Concentration in µg/L

Station ID	Depth	Sample ID	Sample Date	Sample Time	PCE (ECC)	PCE (PID)	TCE (ECC)	TCE (PID)	C12DCE	T12DCE	11DCA	11DCE (ECC)	11DCE (PID)	VC	111TCA	112TCA	TCTFA	CT	CHCL3	12DCEP	MeCL3	TPH	Benzene	Toluene	Ethylbenzene	Total Xylenes
24-00004	12	814501064	07/04	16:22	1U		1U		1.2	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00004	12	814501064	07/04	16:22	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00004	20	814501064	07/04	16:21	1U		1U		1.4	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00005	12	814501065	07/04	14:24	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00005	20	814501065	07/04	14:22	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00006	12	814501066	07/04	14:46	1U		1U		1.2	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00006	18	814501066	07/04	14:50	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00007	12	814501067	07/04	16:19	1U		1U		1U	1U	1U	3.5		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00007	20	814501067	07/04	16:22	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00008	12	814501068	07/04	16:44	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00008	20	814501068	07/04	16:50	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00009	12	814501069	07/04	16:33	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00009	12	814501080	07/04	16:35	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00010	12	814501081	07/04	0:48	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00011	10	814501082	07/04	0:51	1U		3.5		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00012	12	814501082	07/04	0:15	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00012	20	814501082	07/04	0:22	1.1		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00013	15	814501083	07/04	14:38	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00013	18	814501083	07/04	14:38	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00014	15	814501084	07/04	13:59	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00015	15	814501085	07/04	14:15	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00017	15	814501087	07/04	14:55	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00018	12	814501088	07/04	0:10	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1.1	1U	1U	10U	1U	1U	1U	1U
24-00018	20	814501088	07/04	0:18	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1.1	1U	1U	10U	1U	1U	1U	1U
24-00019	12	814501089	07/04	0:36	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1.1	1U	1U	10U	1U	1U	1U	1U
24-00019	20	814501089	07/04	0:40	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1.1	1U	1U	10U	1U	1U	1U	1U
24-00020	12	814501090	07/04	0:08	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1.1	1U	1U	10U	1U	1U	1U	1U
24-00020	20	814501090	07/04	0:16	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1.1	1U	1U	10U	1U	1U	1U	1U
24-00021	12	814501091	07/04	0:08	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1.1	1U	1U	10U	1U	1U	1U	1U
24-00021	20	814501091	07/04	0:16	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1.1	1U	1U	10U	1U	1U	1U	1U
24-00022	12	814501092	07/04	11:50	1U		40.5 E	42.0 F	8	1U	1U	100 E	11.0 F	5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00022	20	814501092	07/04	11:56	1U		50.5 E	100 F	8.5	1U	1.0	491 E	10.7 F	5U	1U	1U	1U	1U	1	1U	1U	10U	2	1U	1U	1U
24-00023	12	814501093	07/04	11:25	1U		1U		1.2	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00023	20	814501093	07/04	11:26	1U		33.7 E	20.0 F	1U	1U	1U	140 E	26.0 F	5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00024	12	814501094	07/04	16:15	1U		2.5		1.6	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00024	20	814501094	07/04	16:22	1U		2.5		1U	1U	1U	26.7 E	3.5 F	5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00025	12	814501095	07/04	16:39	1U		2.7		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00025	20	814501095	07/04	17:07	1U		1		1U	1U	1U	1U		5U	1U	1U	1U	3.1	1U	1U	1U	10U	1U	1U	1U	1U
24-00026	12	814501096	07/04	17:07	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1.2	1U	1U	1U	10U	1U	1U	1U	1U
24-00026	20	814501096	07/04	16:29	1U		1U		1U	1U	1U	1.4		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00027	12	814501097	07/04	16:29	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00027	12	814501097	07/04	14:53	1U		1.9		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00027	20	814501097	07/04	16:01	1U		2.5 E	1.3 F	1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00028	12	814501098	07/04	0:44	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00028	20	814501098	07/04	0:40	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00029	15	814501099	07/04	0:23	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00029	15	814501099	07/04	15:20	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00031	15	814501101	07/04	15:40	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00032	12	814501102	07/04	10:26	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	2.5	1U	1U	1U	10U	1U	1U	1U	1U
24-00032	20	814501102	07/04	10:41	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00033	15	814501103	07/04	14:30	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00034	15	814501104	07/04	15:02	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00035	15	814501105	07/04	16:30	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00035	15	814501105	07/04	15:41	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00035	15	814501105	07/04	16:12	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U
24-00035	15	814501105	07/04	14:30	1U		1U		1U	1U	1U	1U		5U	1U	1U	1U	1U	1U	1U	1U	10U	1U	1U	1U	1U

**FINAL**

**EXTRACTS**

**GROUNDWATER MONITORING REPORT  
JULY 1997 SAMPLING ROUND**

**GROUNDWATER MONITORING PROGRAM  
FOR  
MARINE CORPS AIR STATION EL TORO  
EL TORO, CALIFORNIA**

**Contract No. N68711-96-D-2029  
Delivery Order 005**

**Prepared for:**

**SOUTHWEST DIVISION  
NAVAL FACILITIES ENGINEERING COMMAND  
1220 Pacific Highway  
San Diego, California 92132**

**Prepared by:**


**CDM FEDERAL PROGRAMS CORPORATION  
3760 Convoy Street, Suite 210  
San Diego, California 92111**

**October 1997**



Table B-1: WATER LEVEL MEASUREMENTS AND GROUNDWATER ELEVATIONS  
MCAS El Toro Groundwater Monitoring Program

STATION ID	WELL TYPE	SCREEN INTERVAL (feet BGS)	TOP OF CASING (feet MSL)	MEASUREMENT DATE	DEPTH TO WATER (feet TOC)	WATER LEVEL ELEVATION (feet MSL)	CHANGE FROM PRIOR (+ or - feet)
08_DGMW74	WT	90 - 130	264.75	14-Feb-96	84.99	179.76	
			266.70	27-Feb-96	85.08	181.62	1.86
			266.70	27-Mar-96	85.24	181.46	-0.16
			266.70	30-Oct-96	85.23	181.47	0.01
			266.70	26-Nov-96	85.04	181.66	0.19
			266.70	26-Dec-96	85.15	181.55	-0.11
			266.70	23-Jan-97	84.80	181.90	0.35
			266.70	26-Feb-97	84.60	182.10	0.20
			266.70	27-Mar-97	84.46	182.24	0.14
			266.70	26-Jun-97	84.60	182.10	-0.14
			266.70	11-Aug-97	84.73	181.97	-0.13
08_UGMW29	WT	95 - 135	271.94	12-Jan-96	87.00	184.94	
			271.94	14-Feb-96	86.75	185.19	0.25
			271.94	27-Feb-96	86.70	185.24	0.05
			271.94	27-Mar-96	86.50	185.44	0.20
			271.94	30-Oct-96	86.46	185.48	0.04
			271.94	26-Nov-96	86.29	185.65	0.17
			271.94	27-Dec-96	86.10	185.84	0.19
			271.94	23-Jan-97	86.02	185.92	0.08
			271.94	26-Feb-97	85.84	186.10	0.18
			271.94	27-Mar-97	85.70	186.24	0.14
			271.94	26-Jun-97	85.82	186.12	-0.12
			271.94	11-Aug-97	85.89	186.05	-0.07
09_DGMW45	WT	117 - 157	280.00	11-Jan-96	118.70	161.30	
			280.00	15-Feb-96	118.44	161.56	0.26
			280.00	27-Feb-96	118.35	161.65	0.09
			280.00	27-Mar-96	118.02	161.98	0.33
			280.00	30-Oct-96	118.64	161.36	-0.62
			280.00	26-Nov-96	118.12	161.58	0.22
			280.00	26-Dec-96	118.07	161.93	0.05
			280.00	23-Jan-97	117.60	162.60	0.67
			280.00	27-Feb-97	118.81	163.19	0.69
			280.00	27-Mar-97	117.24	162.76	-0.43
			280.00	26-Jun-97	118.00	162.00	-0.76
			280.00	11-Aug-97	118.06	161.94	-0.06
09_DGMW75	WT	114 - 154	271.00	11-Jan-96	112.68	158.32	
			271.00	14-Feb-96	112.20	158.80	0.48
			271.00	27-Feb-96	112.21	158.79	-0.01
			271.00	27-Mar-96	111.90	159.10	0.31
			271.00	1-Nov-96	112.47	158.53	-0.57
			271.00	26-Nov-96	111.93	159.07	0.54
			271.00	26-Dec-96	111.93	159.07	0.00
			271.00	27-Feb-97	110.82	160.18	1.11
			271.00	27-Mar-97	111.21	159.79	-0.39
			271.00	26-Jun-97	111.74	159.26	-0.53
			271.00	11-Aug-97	111.83	159.17	-0.09
10_DGMW77	WT	130 - 170	271.40	11-Jan-96	104.60	166.80	
			271.40	14-Feb-96	104.78	166.62	-0.18
			271.40	27-Feb-96	104.75	166.65	0.03
			271.40	27-Mar-96	104.34	167.06	0.41
			271.40	30-Oct-96	104.68	166.72	-0.34
			271.40	26-Nov-96	104.25	167.15	0.43
			271.40	26-Dec-96	104.30	167.10	-0.05
			271.40	23-Jan-97	103.82	167.58	0.48
			271.40	26-Feb-97	103.45	167.95	0.37
			271.40	27-Mar-97	103.60	167.80	-0.15
			271.40	26-Jun-97	103.98	167.42	-0.38
			271.40	12-Aug-97	104.14	167.26	-0.16



Source of Information:  
 Final Groundwater Monitoring Report, July 1997  
 Sampling Round, Groundwater Monitoring  
 Program for Marine Corps Air Station, El Toro  
 (CDM Federal Programs Corporation, 1997).

NOTE: Contours represent lines of equal trichloroethylene  
 (TCE) concentrations in micrograms per liter.

United States Marine Corps

**EXTRACTS**

# **Base Realignment and Closure Cleanup Plan (BCP)**



**For  
Marine Corps Air Station  
El Toro, CA**

**March 1998**

Table 3-1a  
Site Summary  
(Sheet 31 of 37)

Seq. No.	Database Tracking	Previous Parcel	New Parcel	Description	Material Disposed	Date of Operation	Status	Risk to Human Health and the Environment <sup>1</sup>	Regulatory Mechanism	NFA	Comments	BCP Area Type <sup>2</sup>
737	RFA 72	5A	A1	< 90-day accumulation area			FA				See Table 3-13	6
738	RFA 74	5A	A1	Aircraft wash area						X	See Table 3-13	1
739	RFA 78	5A	A1	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
740	RFA 79	5A	A1	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
741	RFA 80	5A	A1	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
742	RFA 81	5A	A1	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
743	RFA 82	5A	A1	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
744	RFA 89	4A	A2	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
745	RFA 94	4B	A4	< 90-day accumulation area			FA				See Table 3-13	6
746	RFA 95	4A	A1	Engine test cell						X	See Table 3-13	3
747	RFA 96	5A	B1	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
748	RFA 98	4B	A4a	Vehicle wash rack						X	See Table 3-13	1
749	RFA 100	4B	A4a	TCE degreaser						X	See Table 3-13	3
750	RFA 103	4B*	A4a	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
751	RFA 104	5A	A4b	< 90-day accumulation area			FA				See Table 3-13	6
752	RFA 105	5A	A4b	< 90-day accumulation area			FA				See Table 3-13	6
753	RFA 106	5A	A4b	< 90-day accumulation area			FA				See Table 3-13	6
754	RFA 109	4A	A1	< 90-day accumulation area			Not Located During RFA			X	See Table 3-13	1*
755	RFA 110	4A	A1	Vehicle wash rack			FA				See Table 3-13	6
756	RFA 120	3A	J4	Vehicle wash rack						X	See Table 3-13	3
757	RFA 121	3A	J4	Drum storage area			Not Located During RFA			X	See Table 3-13	1*
758	RFA 125	2B	I2	< 90-day accumulation area						X	See Table 3-13	3
759	RFA 128	4A	A1	Storage area						X	See Table 3-13	1*
760	RFA 131	3A	B1	Engine test cell			Transfer to RAC Remediation (impacted soils were removed in 1997)				See Table 3-13	6
761	RFA 133	3A	B1	< 90-day accumulation area			Not Located During RFA			X	See Table 3-13	1*
762	RFA 134	3A	B1	< 90-day accumulation area			Not Located During RFA			X	See Table 3-13	1*
763	RFA 136	5A	B1	Aircraft wash area						X	See Table 3-13	1
764	RFA 141	5A	B1	Aircraft wash area						X	See Table 3-13	1

Final BRAC Cleanup Plan  
MCAS El Toro, CA

3-79

FORM 136 JAN 2004  
March 1998

UNCLASSIFIED

UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE

