

Found crane had hit the high voltage wires on the poles shown behind the crane



Crane accident: No injuries and there does not appear to be any damage to government property. Job on safety stand down. Crane removed and re certified. Operator removed. Lesson: Operator did not set the brake allowing boom to drift into power line.



Position of the crane when arrived on site



The cable has clearly been burned or shorted and the damage can be seen.




Another angle of the same crane cable.



High voltage, 11,500 volt, that the crane struck. No visible damage to the cable. We will have it checked.



Picture of crane certification mounted on crane



# Compliance Survey

**TIDEWATER TESTING SERVICES**  
375 POPLAR LAWN RD. SURRY, VA 23888  
(757) 294-5112

**COMPLIANCE SURVEY**

DATE OF SURVEY	TYPE OF SURVEY
MANUFACTURER	SERIAL NO.
SERVER	

BY ISSUANCE OF THIS RELEASE, THE DEVICE HAS BEEN EXAMINED AND FOUND TO BE IN COMPLIANCE WITH FEDERAL AND OTHER STANDARDS IN EFFECT AS OF THIS DATE.

ACCREDITED UNDER PART 1000  
U.S. DEPT. OF LABOR

**TIDEWATER TESTING SERVICES**  
375 POPLAR LAWN RD. SURRY, VA 23888  
(757) 294-5112