

N62604.AR.000728
NCBC GULFPORT
5090.3a

PRESENTATION SLIDES FROM RESTORATION ADVISORY MEETING REGARDING
AGREED ORDER AND INSTALLATION RESTORATION PROGRAM UPDATE NCBC
GULFPORT MS
8/5/2008
NAVFAC SOUTHEAST DIVISION

Agreed Order and Installation Restoration Program Update

August 2008

Art Conrad
Navy RAB Co-Chair



Site 1 – Disaster Recovery Disposal Area Landfill

- Site 1 is an inactive landfill where a mock disaster recovery training area is currently located.
- The landfill was used from 1942-1948.
- The Remedial Investigation is nearing completion and report is underway.
- A Feasibility Study is underway and funds have been requested for the Proposed Plan, Decision Document and Remedial Design.



Site 2 – World War II Landfill

- Site 2 is an inactive landfill where general refuse generated at the base was disposed.
- The landfill was used from 1942-1948.
- A Remedial Investigation is now planned to begin in early 2009.

RAB



Gulfport, Mississippi

Site 3 – The Northwest Landfill and Burn Pit

- Site 3 is an inactive landfill that was the primary disposal area from 1948-1968.
- A burn pit on site was used for fire-fighting training from the mid-1950's to 1966.
- The Remedial Investigation fieldwork is completed and a report is in review.
- A Feasibility Study is underway and the Proposed Plan, Decision Document and Remedial Design are funded.

RAB



Site 4 – Golf Course Landfill

- Site 4 operated as a landfill from 1966-1972.
- A Remedial Investigation and Feasibility Study have been completed and the reports are in review.
- Proposed Plan, Decision Document and Remedial Design are underway but waiting for RI/FS approval and planned for FY09.

RAB



Gulfport, Mississippi

Site 5 – Equipment Training Area Landfill

- The landfill located at Site 5 operated from 1972-1976.
- A Remedial Investigation and Feasibility Study are complete and awaiting final approval.
- The Proposed Plan, Public Comment Period are complete and the Decision Document and Remedial Design are underway.

RAB



Gulfport, Mississippi

Site 6 – Fire Fighting Training Area

- Site 6 contained two fire-fighting training pits which operated between 1966 and 1975.
- An enhanced bio-slurper system has ended productive removals.
- The bioslurper has been dismantled and the site restored.
- Long-term monitoring to evaluate the progress of natural attenuation at the site has begun.

RAB



Gulfport, Mississippi

Site 7 – Rubble Disposal Area

- This 3-acre site reportedly received only construction rubble from 1978-1984.
- A Remedial Investigation is now planned for early 2010.

RAB



Gulfport, Mississippi

Site 8 - The Former Herbicide Orange Storage Area

- Project includes locating, excavating, and stabilizing dioxin contamination resulting from the storage of Herbicide Orange on Site 8.
- The stabilized material on Site 8A was covered with 12 inches of Roller Compacted Concrete (RCC) providing a 13 acre area for storing heavy equipment.
- Excavated ditches on base have been restored.
- Excavated areas off base have been filled, mulched, seeded and planted for restoration as a wetlands.

RAB



Gulfport, Mississippi

Site 8 - The Former Herbicide Orange Storage Area

- Low level dioxin contaminated material was found along Canal Road. An engineering evaluation was completed and the contaminated soil has been excavated, transported to Site 8, compacted and solidified with concrete to prevent erosion.
- Other areas along the Canal/Turkey Creek are under investigation and a second sampling plan is in review.

RAB



Gulfport, Mississippi

Site 10 – Parade Ground Ditch

- PCBs were found in the ditches of the NCBC Gulfport parade ground.
- Remedial actions were taken in 1999 to remove the source of PCB contamination.
- The Remedial Investigation/Feasibility Study, Proposed Plan, Public Comment Period, Decision Document are complete.
- Remedial Actions are contracted but the site is under review for optimization.

RAB



Gulfport, Mississippi