

N62604.AR.001849  
NCBC GULFPORT  
5090.3a

LETTER REGARDING RESTARTING BURNERS THAT FLAMED OUT DUE TO SEVERE  
WEATHER NCBC GULFPORT MS  
2/16/1988  
TYNDALL AIR FORCE BASE



DEPARTMENT OF THE AIR FORCE  
HEADQUARTERS AIR FORCE ENGINEERING AND SERVICES CENTER  
TYNDALL AIR FORCE BASE, FL 32403

16 FEBRUARY 1988

Reply to attn of: RDVW (Maj Stoddart)

Subj: Report of Process Interruption

To: Ms Caron Falconer  
EPA Region IV  
345 Courtland Street  
Atlanta, Georgia 30365

1. On 15 Feb 88 , during severe weather, the Kiln and SCC flamedout (see attached letter). Both burners were restarted and both furnaces returned to normal operating temperatures within 21 minutes. During the flameout both the packed tower and the jet scrubber were in operation. In my opinion there was no environmental release of materials from the incinerator.

2. If you have any questions, please contact me at tele:  
904-283-2942.

A handwritten signature in cursive script that reads "T L Stoddart".

Terry L Stoddart, Maj, USAF, BSC  
Chief, Environmental Restoration R&D