N40003.AR.002298
PUERTO RICO NS
5090.3a

LETTER DISCUSSING INSTALLATION OF COMMUNICATION CABLE AT ROOSEVELT ROADS AND TRANSMITTING MAP OF SITE 15 NAVAL ACTIVITY PUERTO RICO
8/18/1994
RIOCC-PRA

METCALF & EDDY

ATLANTA OFFICE

TELECOPIER TRANSMITTAL SHEET - PLEASE DELIVER IMMEDIATELY

DATE: 8/18/94

NAME: Jim Szykman
LOCATION: NAVFAC
FROM: Rob MacPherson

COMMENTS/NOTES:

CC: _____ _____
_____ _____

TOTAL NUMBER OF PAGES TRANSMITTED (INCLUDING COVER SHEET): _____
PLEASE CALL 404-881-8010 IF YOU DO NOT RECEIVE TOTAL NUMBER OF PAGES LISTED

FOR ATLANTA OFFICE USE ONLY:

DO YOU WANT ORIGINAL BACK? YES ____ NO ____

JOB NUMBER: ☐☐☐☐☐☐ ☐☐☐☐ ☐☐☐

JOB NAME: _____

1201 PEACHTREE STREET, N.E. SUITE 1101/400 COLONY SQUARE /ATLANTA, GA. 30361
(404)881-8010 / FAX (404)872-3161

AWT Affiliates of Air & Water Technologies Corporation

FACSIMILE TRANSMISSION COVER SHEET

DEPARTMENT OF THE NAVY

RESIDENT OFFICER IN CHARGE OF CONSTRUCTION PUERTO RICO AREA

NUMBER OF PAGES (Including Cover Sheet) 3 **DATE:** 8/18/94

TO: Robert R. Mopherson, P.E.
Metcalf & Eddy

FROM: Francisco Cortez
ROICC PRA CODE c63

PHONE NO.: (809) 865-2050

FAX NO. (404)872-3161 **FAX NO.:** (809) 865-2018

SUBJECT: Telephone line installation

ENCLOSURE: Site 15, map showing cable route

REFERENCE: Contract #92-D-3042 Remedial of Contaminated Soil Sites 15 & 16, Roosevelt Roads PR

REMARKS:

The NAVSTA Roosevelt Roads is installing a communication cable. The cable will run along Forrestal Drive to connect to the existing communication manhole at the South and East side of site 15 of the above referenced project.

A meeting was held to discuss new cable routing in the possible contaminated soil area. Please verify and provide test results to determine no contamination exists in the trenched area shown on enclosed map of site 15.

Below is a list of people present in the above mentioned meeting:

Joe- MILCON Rep. (KTR)
Chief Graham- Telephone Exchange
Tony Rivera- Telephone Exchange
Frank Cortez- ROICC PRA

Please contact me at your earliest convenience.

Sincerely,

Francisco Cortez


encl. (1)
30'
25'
6' TREE
SUPPORT ZONE
12" TREE
INSTALL 14' DOUBLE SWING GATE. SEE DETAIL SHEET C-14.
40 MPH/SIGN
TEMPORARY 12" R.C.P. /DRAINAGE CULVERT
TCE
DECON PIT - SEE DETAILS SHT. C-14. DECON ZONE
3.0'
DECON ZONE
HB
EXCLUSION ZONE
TRANSFORMER PAD
EXISTING 8' CHAIN LINK FENCE (TYP.)
GRASS
To TEL. M.H
EXCLUSION ZONE
SIGN
BP
U.G. TEL. COND.
SWALE
4" PVC
EFM
EOE
ES
15"
DROP INLET
TOP EL. 108.70
INV. EL. 103.70
STA. A
STOP SIGN
(TO BE RELOCATED)
30" ED
VALLEY FORGE RO
(BITUMINOUS CONCRET

AUG 18 '94 15:04 08.18.94 11:26 AM *OICC/ROICC PRA PAGE.003 PU2

encl. (2)