

N60200.AR.005504
NAS CECIL FIELD
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
COMMENTS ON SOURCE REMOVAL REPORT EXCAVATION OF PETROLEUM
CONTAMINATED SOIL AT BUILDINGS 502 AND 290A NAS CECIL FIELD FL
01/20/2011
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Florida Department of Environmental Protection

Bob Martinez Center
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Rick Scott
Governor

Jennifer Carroll
Lt. Governor

Herschel T. Vinyard, Jr.
Secretary

January 20, 2011

BRAC PMO SE
Attn: Mr. Art Sanford
4130 Faber Place Drive
Suite 202
North Charleston, SC 29405

RE: Source Removal Report, Excavation of Petroleum Contaminated Soil at Buildings 502 and 290A, Revision No. 00, Former Naval Air Station Cecil Field, Jacksonville, Florida.

Dear Mr. Sanford:

I have completed my review of the Source Removal Report, Excavation of Petroleum Contaminated Soil at Buildings 502 and 290A, Revision No. 00, Former Naval Air Station Cecil Field, dated November 2010, respectively (received November 4, 2010), prepared and submitted by CH2M Hill Constructors, Inc. I have the following comments on the report:

- (1) There is no discussion of the abandonment of well CEF-502-1SR. This well must have been abandoned prior to or during the excavation at Building 502. According to Tetra Tech NUS's Post-Excavation Groundwater Monitoring Report for Building 502 (November 24, 2010), they installed monitoring well CEF-502-9S to replace CEF-502-1SR, which was abandoned during excavation activities.
- (2) Please provide figures that show the actual excavations conducted rather than figures showing what was proposed to be excavated in the Dig and Haul Packages. The figures should also depict the confirmatory soil sampling locations that bound the excavations. Lastly, tables with the soil analytical results, that in conjunction with the figures document the cleanup of soil at the site to levels protective for unrestricted use, should be provided. For the Building 502 site the figure and table can incorporate the data from the tank removal or they may remain separate. Please note that these figures and tables will be attached as exhibits to a Site Rehabilitation Completion Order for the sites once all the requirements of Section 62-770.680, Florida Administrative Code, are met.

Art Sanford
Source Removal Report at Buildings 502 and 290A
Page 2 of 2
January 20, 2011

If you have any concerns regarding this letter, please contact me at (850) 245-8997.

Sincerely,



David P. Grabka, P.G.
Remedial Project Manager
Federal Programs Section
Bureau of Waste Cleanup

CC: Debbie Vaughn-Wright, EPA Region 4, Atlanta
John Flowe, City of Jacksonville
Rob Simcik, TtNUS, Pittsburgh
Mike Halil, CH2M Hill, Jacksonville
Mike Fitzsimmons, FDEP, Northeast District

JJC  ESN 