

N60200.AR.003837  
NAS CECIL FIELD, FL  
5090.3a

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION COMMENTS ON SECOND  
QUARTER 2003 OPERATIONS AND MAINTENANCE REPORT FOR BIOSPARGING/SOIL  
VAPOR EXTRACTION SYSTEM AT DAY TANK 1 NAS CECIL FIELD FL  
2/24/2004  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

February 24, 2004  
OFFICIAL CORRESPONDENCE

Commanding Officer  
attn: Mr. Gabe Magwood, Code ES24  
Southern Division  
Naval Facilities Engineering Command  
Post Office Box 190010  
North Charleston, SC 29419-9010

Dear Mr. Magwood:

I have completed my review of the Second Quarter 2003 Operations and Maintenance Status Report for the period of April 1, 2003 – June 30, 2003, for the Biosparging and Soil Vapor Extraction System, Day Tank 1 Site, Naval Air Station Cecil Field, dated November 2003 (received February 19, 2004), prepared and submitted by Terraine Environmental Services, Inc. The report incorrectly states that contaminant concentrations for all monitoring wells were below the Department's groundwater cleanup target levels. In Table 3-4 and the June 2003 Laboratory Analytical Reports for Groundwater Samples in Appendix B, the analytical results for monitoring well show that the petroleum contaminants benzene and xylenes (total) were detected at concentrations above their groundwater cleanup target levels.

This electronic message is being sent in lieu of regular mail. If you have any questions concerning this review, please contact me at (850)245-8997.

Sincerely,

David P. Grabka, P.G.  
Remedial Project Manager  
MS4535  
Florida Department of Environmental Protection  
2600 Blair Stone Road  
Tallahassee, FL 32399-2400  
Direct: 850.245.8997  
FAX: 850.245.8703  
david.grabka@dep.state.fl.us