

N61165.AR.005542
CNC CHARLESTON
5090.3a

LETTER REGARDING SOUTH CAROLINA DEPARTMENT OF HEALTH AND
ENVIRONMENTAL CONTROL REVIEW OF SECOND QUARTER 2001 MONITORING
REPORT RECEIVED 7 SEPTEMBER 2001 FOR ZONE H SITE 02 BUILDING NS-53 CNC
CHARLESTON SC
09/10/2001
SOUTH CAROLINA DEPARTMENT OF HEALTH AND ENVIRONMENTAL CONTROL



10 September 2001

2600 Bull Street
Columbia, SC 29201-1708

COMMISSIONER:
Douglas E. Bryant

BOARD:
Bradford W. Wyche
Chairman

William M. Hull, Jr., MD
Vice Chairman

Mark B. Kent
Secretary

Howard L. Brilliant, MD

Brian K. Smith

Louisiana W. Wright

Larry R. Chewning, Jr., DMD

DEPARTMENT OF THE NAVY
SOUTHERN DIVISION NAVAL FEC
GABRIEL MAGWOOD
P.O. BOX 190010
N. CHARLESTON SC 29419-9010

Re: Zone H, Site 02 Building NS 53
Site Identification # 00957
Second Quarter 2001 Monitoring Report received 07 September 2001
Charleston County

Dear Mr. Magwood:

The Department has completed technical review of the referenced document. Interpretation of the analytical data provided in the referenced report indicates that chemicals of concern are above established Risk-Based Screening Levels and MCLs due to the presence of a hydrocarbon sheen in sample location CNC02-P02. The Department does not concur with the recommendation that this site be issued a no further action at this time. Routine groundwater monitoring and reporting should continue as prescribed in the Corrective Action Plan dated December 2000. The Navy may wish to consider active corrective action measures at this site to eliminate the hydrocarbon sheen present in CNC02-P02.

Should you have any questions, please contact me at 803-898-3553 (office phone), 803-898-3795 (fax) or bishopma@columb32.dhec.state.sc.us.

Sincerely,

Michael Bishop, Hydrogeologist
Groundwater Quality Section
Bureau of Water

cc: Trident District EQC
Paul Bergstrand - SCDHEC BLWM
Technical File