

DEPARTMENT OF HEALTH SERVICES

2151 BERKELEY WAY  
BERKELEY, CA 94704



November 6, 1986

Mr. Alex Dong  
Naval Facilities Engineering Command  
P.O. Box 727  
San Bruno, CA 94066

Dear Mr. Dong:

In phone conversations on October 29, 1986 between Mr. Alan Lui, Mr. Greg Brown of your Command, and myself, it was reported that an additional site of contamination has been discovered at the Hunters Point Naval Shipyard.

It is our understanding that during excavation activities in the vicinity of Building 505, potential PCB contamination was found in the soil. Results from utilization of field test kits indicated levels as high as 4000 ppm PCB. We further understand that samples were taken for laboratory analysis and confirmation, and that the results will be forwarded to our office as soon as possible.

Mr. Brown stated to us that this site will be added to the Navy Assessment and Control of Installation Pollutants (NACIP) Program. We request that you confirm this information and commitment in writing. Thank you.

Sincerely,

*Robert A. Crandall*

Robert A. Crandall  
Hazardous Materials Specialist

RC:cdl