

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD

SAN FRANCISCO BAY REGION

111 JACKSON STREET, ROOM 6040
OAKLAND 94607

Phone: Area Code 415
464-1255



September 12, 1984
File No. 2129.2011B(LWT)omt

Mr. Ralph M. Lee
Environmental Engineer
Mare Island Naval Shipyard
Public Works Department
Vallejo, Ca. 94592

Dear Mr. Lee:

In our meeting on September 6, 1984, Mr. Steven Ritchie mentioned a draft of the new subchapter 15 regulations and its possible applicability to the Mare Island landfill when it is adopted. Enclosed is a copy of the draft you requested. Please make additional copies if you need them.

I would like to take this opportunity to review and confirm some of the conclusions we reached at the meeting:

- 1) Soil samples at the 900 area should be included in the verification step.
- 2) Details for classification of the contamination at berths 4 and 5 can be better addressed after the verification step.
- 3) A ground water monitoring system and ground water monitoring data for the landfill to comply with Mare Island's ISD Permit will be submitted to us by the end of October 1984.
- 4) The cause (biological or chemical) of pH violations for the hydraulic) dredging effluent will be determined.
- 5) And a report on PCB clean-up activities for sites 8,9,10 and 11 will be submitted to us.

We also agreed that placement of ground water monitoring wells around the Industrial Waste Treatment Plant needs further discussion.

You mentioned that soil samples were made around tank 772, please provide a report of the results.

Mr. Rich Seraydrian said at the meeting that West Div's contract with the consulting firm of Richesin and Associates will be finalized in 3 to

8709 1799


Mr. Ralph M. Lee

-2-

September 12, 1984

4 weeks. I look forward to talking to you again at that time. Meanwhile, I would appreciate prompt attention to the matters discussed above. If you have any questions please call me at (415)464-0990.

Sincerely,



Lila W. Tang
Water Resource Control Engineer

Enclosure

cc: Rich Seraydarian, West Div (w/o Enclosure)

ENCLOSURE

DRAFT NEW SUBCHAPTER 15 REGULATIONS

THIS ENCLOSURE WAS NOT RECEIVED IN THE
RESTORATION RECORD FILE.

FOR ADDITIONAL INFORMATION, CONTACT:

DIANE C. SILVA, COMMAND RECORDS MANAGER, CODE EV33
NAVAL FACILITIES ENGINEERING COMMAND, SOUTHWEST
1220 PACIFIC HIGHWAY (NBSD BLDG. 3519)
SAN DIEGO, CA 92132

TELEPHONE: (619) 556-1280

E-MAIL: diane.silva@navy.mil