



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthorne Street
San Francisco, Ca. 94105-3901

November 5, 1992

Steven Chao
Western Division
Naval Facilities Engineering Command
900 Commodore Way, Bldg. 101
San Bruno, CA 94066-0720

Dear Mr. Chao:

The U.S. Environmental Protection Agency has reviewed the Runway Well Abandonment Report for the Naval Air Station Moffett Field NPL site. Based on the review of our representative, SAIC, Inc., we have no comments to offer regarding this report. SAIC's comment letter is attached. Please call me if you have any questions, at (415) 744-2385.

Sincerely,

A handwritten signature in cursive script that reads "Roberta Blank".

Roberta Blank
Remedial Project Manager

cc: Elizabeth Adams, RWQCB
Cyrus Shabahari, DTSC



Science Applications International Corporation
An Employee-Owned Company

Technology Services Company

November 3, 1992

DCN: TZ4-C09015-RN-M15209

Ms. Roberta Blank (H-9-2)
U.S. Environmental Protection Agency
Region IX
75 Hawthorne Street
San Francisco, CA 94105

Ref: EPA Contract No. 68-W9-0008; Work Assignment No. C09015
SAIC/TSC Project No. 06-0794-03-0630
Runway Well Abandonment Report

Dear Roberta:

SAIC/TSC has completed its technical review of the Runway Well Abandonment Report. The review was performed by Mary Wesling, SAIC/TSC Geologist.

The field operations and technical decisions in the well abandonment, as detailed in the report, followed accepted practices and guidelines for sealing and abandoning wells. After logging the well, James M. Montgomery, Inc. (JMM) and PRC Environmental Management, Inc. (PRC) consulted with Mr. Tom Iwamura, Santa Clara Valley Water District (SCVWD) Engineering Geologist, to determine the appropriate intervals for annular seals. Mr. David Zozaya, SCVWD Senior Water Resources Technician, was present and gave the District's approval during all phases of the well abandonment.

The groundwater sampling at the well abandonment was reviewed and approved by the California Regional Water Quality Control Board (RWQCB). Analytical reports, included as Appendix C, showed all analytes to be below detectable levels.

Based on the level of oversight by the SCVWD and the RWQCB during abandonment of the well and on our review of the report, the well was properly sealed and abandoned.

If you have any questions, please give me a call at (415) 399-0140.

Sincerely,

SCIENCE APPLICATIONS INTERNATIONAL CORPORATION
Technology Services Company

A handwritten signature in cursive script that reads "Fred Molloy". The signature is written in dark ink and is positioned above the typed name and title.

Fred Molloy
Work Assignment Manager