

DEPARTMENT OF TOXIC SUBSTANCES CONTROL

SECTION 2  
700 HEINZ AVE., SUITE 200  
BERKELEY, CA 94710-2737

(510) 540-3724



April 26, 1995

Commander  
Department of the Navy  
Engineering Field Activity, West  
Naval Facilities Engineering Command  
Attn: Mr. Stephen Chao, Project Manager  
900 Commodore Drive, Bldg. 101  
San Bruno, California 94066-2402

Dear Mr. Chao:

**FINAL NAVAL EXCHANGE GASOLINE STATION (NEX) INVESTIGATION  
TECHNICAL MEMORANDUM, MOFFETT FEDERAL AIRFIELD (FORMERLY NAVAL  
AIR STATION MOFFETT FIELD)**

The Department of Toxic Substances Control (DTSC) and the San Francisco Regional Water Quality Control Board (RWQCB) have reviewed the subject document. The State has previously mentioned that if a hazardous substance release and a petroleum product release are commingled, then the entire release should be investigated and remediated under the ongoing CERCLA response action process. Please explain why the commingled plume at Sump 25 area is under the petroleum sites corrective action. If you have any questions, please contact me at (510) 540-3830.

Sincerely,

A handwritten signature in cursive script, appearing to read "C. Joseph Chou".

C. Joseph Chou  
Remedial Project Manager  
Base Closure Unit  
Office of Military Facilities

cc: Mr. Michael Bessette  
Regional Water Quality Control Board  
2101 Webster Street, Suite 500  
Oakland, California 94612

Mr. Michael D. Gill  
U.S. Environmental Protection Agency  
Region IX, Mail Stop H-9-2  
75 Hawthorne Street  
San Francisco, California 94105

2239

