

DEPARTMENT OF TOXIC SUBSTANCES CONTROL

ROOM 2
700 HEINZ AVE., SUITE 200
BERKELEY, CA 94710-2737

N00296.002240
MOFFETT FIELD
SSIC NO. 5090.3



(510) 540-3724

April 26, 1995

Commander
Department of the Navy
Engineering Field Activity, West
Naval Facilities Engineering Command
Attn: Mr. Stephen Chao, Project Manager
900 Commodore Drive, Bldg. 101
San Bruno, California 94066-2402

Dear Mr. Chao:

**FINAL ADDITIONAL PETROLEUM SITES INVESTIGATION TECHNICAL
MEMORANDUM, MOFFETT FEDERAL AIRFIELD (FORMERLY NAVAL AIR STATION
MOFFETT FIELD)**

The Department of Toxic Substances Control (DTSC) and the San Francisco Regional Water Quality Control Board (RWQCB) have reviewed the subject document. The State has previously mentioned that if a hazardous substance release and a petroleum product release are commingled, then the entire release should be investigated and remediated under the ongoing CERCLA response action process. Please explain why the commingled plumes at Tanks 2 and 43 are under the petroleum sites corrective action. If you have any questions, please contact me at (510) 540-3830.

Sincerely,

A handwritten signature in cursive script that reads "C. Joseph Chou".

C. Joseph Chou
Remedial Project Manager
Base Closure Unit
Office of Military Facilities

cc: Mr. Michael Bessette
Regional Water Quality Control Board
2101 Webster Street, Suite 500
Oakland, California 94612

Mr. Michael D. Gill
U.S. Environmental Protection Agency
Region IX, Mail Stop H-9-2
75 Hawthorne St.
San Francisco, California 94105

22A0

