



DEPARTMENT OF THE NAVY  
SOUTHWEST DIVISION  
NAVAL FACILITIES ENGINEERING COMMAND  
1220 PACIFIC HIGHWAY  
SAN DIEGO, CA 92132-5190

N00247.000055  
NTC SAN DIEGO  
SSIC #5090.3

5090  
Ser 1851.JM/3085  
25 Oct 93

From: Commanding Officer, Southwest Division, Naval Facilities Engineering  
Command  
To: Commander, Naval Training Center, San Diego (010.2)  
Subj: 19F5 FIRE FIGHTING TRAINER SOURCE EMISSION TESTING  
Ref: (a) SOUTHWESTNAVFACENGCOM ltr 5090 Ser 1851.JM/3032 of 7 Oct 93  
Encl: (1) BTC Environmental Incorporated ltr of 2 Sep 93  
(2) BTC Environmental Incorporated Source Test Plan of 3 Aug 93  
(3) BTC Environmental Incorporated Site Safety Plan

1. The reference informed that the San Diego Air Pollution Control District (APCD) require further source testing of the subject trainer for the criteria pollutants and toxics listed in enclosures (1) and (2). Results of this testing will be used to determine whether the activity is granted an operating permit; moreover, the results, if satisfactory, will be reference when burn-parameters are evaluated at other Navy fire fighting trainers.

2. Testing previously scheduled for 12-15 October 1993, was postponed because of potential fire hazard had welding on the smoke stack occurred. During the rescheduled test period, 3 and 4 November 1993, the source test contractor, BTC Environmental Incorporated will attach prefabricated sampling supports onto the smoke stack by drilling and/or sawing in lieu of welding. Holes made in the stack during this procedure will be subsequently capped.

3. Setup for the forthcoming operation will begin at 1000 on 2 November 1993; and testing will commence at approximately 0630, 3 and 4 November 1993 and will be observed by personnel from Southwest Division and the APCD. Per the Activity's request enclosure (3) is provided.

4. We request that base access passes be reserved for the following personnel:

Mr. Tom Porter, BTC  
Mr. Ken Robison, BTC  
Mr. Ken Kennepohl, BTC  
Mr. Ian Morris, Evaluator, APCD

5. If there are any questions or comments, please contact Mr. Julius Miller, Code 1851.JM, at (619) 532-1148 (DSN 522-1148).

  
JULIUS MILLER  
By direction

Copy to: (w/o encl)  
CO, RTC

ENCLOSURES 1 THROUGH 3

MEMO STATING NEED FOR FURTHER SOURCE  
TESTING AT THE 19F5 FIRE FIGHTER TRAINER

THE ABOVE IDENTIFIED ENCLOSURES ARE NOT  
AVAILABLE.

EXTENSIVE RESEARCH WAS PERFORMED BY  
SOUTHWEST DIVISION TO LOCATE THESE  
ENCLOSURES. THIS PAGE HAS BEEN INSERTED  
AS A PLACEHOLDER AND WILL BE REPLACED  
SHOULD THE MISSING ITEM BE LOCATED.

QUESTIONS MAY BE DIRECTED TO:

**DIANE C. SILVA**  
**RECORDS MANAGEMENT SPECIALIST**  
**SOUTHWEST DIVISION**  
**NAVAL FACILITIES ENGINEERING COMMAND**  
**1220 PACIFIC HIGHWAY**  
**SAN DIEGO, CA 92132**

**TELEPHONE: (619) 532-3676**