

## W2 WESTMONT 100-TON FLOATING CRANES

<b>Mandatory</b>	<b>Date Issued</b>	<b>Classification</b>	<b>Title</b>
N3258A-W2-015	16-Mar-14	Delayed - B	Addition of Pendulum Type Radius Indicator
N3258A-W2-014	3-Jun-14	When Needed	Replacement of Whip Hoist Limit Switch Weight and Cable
N3258A-W2-013A	21-Mar-11	Delayed - B	Addition of hoist limit switches to diesel stop circuit
N3258A-W2-013	20-Jan-11	Delayed - B	Addition of hoist limit switches to diesel stop circuit
N3258A-W2-012	24-Jun-10	Delayed - B	Replacement of DC control power circuit breaker
N3258A-W2-011	27-Aug-07	When Needed	Replacement of function master switches
N3258A-W2-010	5-Dec-06	Delayed - B	Documentation (as built variance) of crane & Barge Power Circuits
N3258A-W2-006C	19-May-05	Delayed - A	Motor mounting flange cap screw failure
N3258A-W2-006B	14-Dec-04	Delayed - A	Motor mounting flange cap screw failure
N3258A-W2-009	23-Jul-04	Delayed - B	Documentation (as built variance) of crane electrical configuration
N3258A-W2-008	3-Nov-03	Delayed - B	Alteration of Hoist Limit Switches
N3258A-W2-007	4-Dec-02	When Needed	Addition of deadman foot switch
N3258A-W2-006A	24-Oct-02	Delayed - B	Motor mounting flange cap screw failure
N3258A-W2-006	11-Oct-02	Delayed - B	Motor mounting flange cap screw failure
N3258A-W2-005	26-Feb-01	When Needed	Addition of collector ring brush holder arm limiter
N62472-W2-004A	22-Mar-99	Delayed - B	Rep main diesel engine single element housing fuel filter
N62472-W2-004	20-Apr-98	Delayed - B	Rep main diesel engine single element housing fuel filter
N62472-W2-003	16-Apr-98	Site Specific	Rep of primary fuse on mason device transformer
N62472-W2-002	3-Apr-98	When Needed	Installation of cab overhead heater
N62472-W2-001	3-Apr-98	When Needed	Alt of spud lock limit switch