

(W2) Westmont 100-Ton Floating Crane Mandatory Alterations

Mandatory Number	Classification	Date Issued	Title
N3258A-W2-013A	Delayed - B	21-Mar-11	Addition of hoist limit switches to diesel stop circuit
N3258A-W2-013	Delayed - B	20-Jan-11	Addition of hoist limit switches to diesel stop circuit
N3258A-W2-012	Delayed - B	24-Jun-10	Replacement of DC Control Power Circuit Breaker
N3258A-W2-011	When Needed	27-Aug-07	Replacement of function master switches
N3258A-W2-010	Delayed - B	5-Dec-06	Documentation (as-built variance) of crane & barge power circuits
N3258A-W2-006C	Delayed - A	19-May-05	Motor mounting flange cap screw failure
N3258A-W2-006B	Delayed - A	14-Dec-04	Motor mounting flange cap screw failure
N3258A-W2-009	Delayed - B	23-Jul-04	Documentation (as-built variance) of crane electrical configuration
N3258A-W2-008	Delayed - B	3-Nov-03	Alteration of hoist limit switches
N3258A-W2-007	When Needed	4-Dec-02	Addition of deadman foot switch
N3258A-W2-006A	Delayed - B	24-Oct-02	Motor mounting flange cap screw failure
N3258A-W2-006	Delayed - B	11-Oct-02	Motor mounting flange cap screw failure
N3258A-W2-005	When Needed	26-Feb-01	Addition of collector ring brush holder arm limiter
N62472-W2-004A	Delayed - B	22-Mar-99	Rep main diesel engine single element housing fuel filter
N62472-W2-004	Delayed - B	20-Apr-98	Rep main diesel engine single element housing fuel filter
N62472-W2-003	Site Specific	16-Apr-98	Rep of primary fuse on mason device transformer
N62472-W2-002	When Needed	3-Apr-98	Installation of cab overhead heater
N62472-W2-001	When Needed	3-Apr-98	Alt of spud lock limit switch