

New York State Department of Environmental Conservation
Building 40—SUNY, Stony Brook, New York 11790-2356

(516)751-7725 or 751-7900
FAX 751-3839

March 31, 1992



P. Budd
- Thomas C. Jorling
Commissioner

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Mr. John Ohlmann
Grumman Aerospace Corporation
Mail Station A03-12
Bethpage, NY 11714

Re: Spill Numbers 82-0923 - Fire Training Area, Calverton, NY
82-1680 - Fuel Depot, Calverton, NY
84-0011 - Fuel Calibration Area, Calverton, NY

Dear Mr. Ohlmann:

A recent review of our files for the above referenced spill areas located at your Calverton facility indicates that we do not have dissolved plume information for all of these areas. This information was previously requested in our letters for each area when we requested floating and dissolved product plume definition prior to the installation of the individual recovery operations.

At present, recovery operations have been installed at the Fire Training Area and the Fuel Calibration Area. In both of these areas the monitoring wells should be sampled for dissolved hydrocarbons by Methods USEPA 602 and USEPA 625 or Method 8020 and 8270. Once this office has received a copy of these sample results the recovery operation may require additional treatment to upgrade these systems.

In addition, the Fuel Depot Area data has been reviewed and it indicates that a recovery system is needed to treat both floating and dissolved product plumes in this area.

Please contact this office within ten (10) days of receipt of this letter and advise us when this data will be provided.

Sincerely,

Walter J. Parish
Walter J. Parish
Environmental Engineer I

WJP:jf
cc: D. Picha
J. Pim, SCDHS

.. OHLMANN

APR 02 1992