

New York State Department of Environmental Conservation
Building 40—SUNY, Stony Brook, New York 11790-2356

(516) 444-0320
FAX # (516) 444-0373



1993
Thomas C. Jorling
Commissioner

CERTIFIED LETTER - RETURN RECEIPT REQUEST

Mr. John Selva
Grumman Corporation
Mail Stop 'D'08-GHQ
Stewart Avenue
Bethpage, New York 11714-3580

Re: Spill #82-0923, Grumman Fire Training Area, Calverton, N.Y.
82-1680, Grumman Fuel Depot, Calverton, N.Y.
84-0011, Grumman Fuel Calibration Area, Calverton, N.Y.

Dear Mr. Selva:

This office has reviewed the latest monitoring well data for the above referenced locations submitted by Miller Environmental Group on your behalf. This data shows consistent floating product in several monitoring wells at each location. Since no active remediation is currently being performed by your company at this time, this Department requests the following:

1. Passive product bailers should be installed in the monitoring wells which consistently show floating product. This should be done to increase the recovery rate by working on a continuous basis.
2. After these bailers have been installed, the monitoring frequency should be reviewed and adjusted to permit the maximum amount of floating product recovery possible.

Please notify this office within five (5) days of receipt of this letter to inform us when this will be done.

Truly yours,

Walter J. Parish
Environmental Engineer I

WJP:ap
cc: P. John
J. Ohlmann, Grumman

J. OHLMANN

DEC 15 1993

Director Corporate Environment &
Technology & Compliance