

North Carolina
Department of Environment and Natural Resources

Division of Waste Management

Michael F. Easley, Governor
William G. Ross Jr., Secretary
Dexter R. Matthews, Director



December 3, 2008

NAVFAC Atlantic
Attn: Gary Tysor
Code: OPCEV
NC/Caribbean IPT, EV Business Line
6506 Hampton Blvd
Norfolk, VA 23508-1273

RE: Comments on the Site 86 Technical Memo
Operable Unit (OU) # 20 MCB Camp Lejeune, NC
Camp Lejeune, NC6170022580
Jacksonville, Onslow County, North Carolina

Dear Mr. Tysor:

The NC Superfund Section has received and reviewed the OU #20 (Site 86) Technical Memo dated November 17, 2008 and has the following comments:

1. The DPT boreholes are marked incorrectly on the figures. They are marked as IR89 and should be IR86.
2. DPT boreholes IR86-IS52 and IR86-IS55 are not shown on the figures. They should be shown on the figures even though they did not indicate the presence of chlorinated solvents.
3. The memo does not indicate that any surface water samples will be taken. If there is water in the drainage ditch then samples should be taken.

If you have any questions or comments, please contact me, at (919) 508-8489 or email to beth.hartzell@ncmail.net

Sincerely,

Elizabeth A. Hartzell
Environmental Engineer
NC Superfund Section

Cc: Bob Lowder, EMD/IR
Gena Townsend, USEPA

1646 Mail Service Center, Raleigh, North Carolina 27699-1646
Phone: 919-508-8400 \ FAX: 919-715-4061 \ Internet: www.enr.state.nc.us