



FRIDLEY MUNICIPAL CENTER • 6431 UNIVERSITY AVE. N.E. FRIDLEY, MN 55432 • (612) 571-3450 • FAX (612) 571-1287

August 16, 1994

PW94-176

Commanding Officer  
Southern Division  
Naval Facilities Engineer Command  
Attention: David Cabiness, Code 1869  
P.O. Box 190010  
North Charleston, SC 29419-9010

Subject: TRC Committee Meeting No. 21

Dear Mr. Cabiness:

I have reviewed the minutes of the TRC committee meeting of June 23, 1994. The following comment is submitted for inclusion to correct Paragraph F6 on Page 5 of the draft minutes:

"... on a city's experience operating one water supply well that pumps ground water from the unconsolidated aquifer. The discharge from this well is treated through a sand filter to minimize scaling problems in the distribution system due to manganese. He said the Jordan aquifer under the NIROP is stated to be contaminated..."

I respectfully request that this correction be noted in the final minutes.

Sincerely yours,

  
John G. Flora  
Director of Public Works

JGF:rsc