

N60200.AR.001545  
NAS CECIL FIELD, FL  
5090.3a

STATUS REPORT FOR BUILDING 810 TANK 810 BASE REALIGNMENT AND CLOSURE  
UNDERGROUND STORAGE TANK AND ABOVEGROUND STORAGE TANK GREY SITES  
NAS CECIL FIELD FL  
11/1/1998  
HARDING LAWSON ASSOCIATES

**STATUS REPORT**

**BUILDING 810 - TANK 810**

**BASE REALIGNMENT AND CLOSURE**

**UNDERGROUND STORAGE TANK AND  
ABOVEGROUND STORAGE TANK GREY SITES**

**NAVAL AIR STATION CECIL FIELD  
JACKSONVILLE, FLORIDA**

**Unit Identification Code N60200**

**Contract No. N62467-89-D-0317/90**

**Prepared by:**

**Harding Lawson Associates  
2590 Executive Center Circle, East  
Tallahassee, Florida 32301**

**Prepared for:**

**Department of the Navy, Southern Division  
Naval Facilities Engineering Command  
2155 Eagle Drive  
North Charleston, South Carolina 29419**

**Bryan Kizer, Code 1842, Engineer-in-Charge**

**November 1998**

STATUS REPORT FOR TANK 810

Harding Lawson Associates, under contract to the Southern Division, Naval Facilities Engineering Command, has prepared this status report for Tank 810. This report summarizes the findings of the Tank 810 removal.

Tank 810 was an aboveground storage tank (AST) located approximately 200 feet east of the north-south runway and east of Building 810, which is a water treatment facilities building. Tank 810 is actually part of Facility 23, a fenced, open-air jet engine test facility. Facility 23 is also located east of Building 810. The AST, which was installed in 1989, had a 5,000 gallon capacity and was used to supply jet propellant (JP)-5 fuel for the jet engine test facility.

Tank 810 was removed on January 22, 1997. A closure report was not prepared for Tank 810 because it was in compliance with state tank regulations. Tank 810 was a double-walled AST which sat on concrete and was enclosed in a walled concrete containment structure. During site visits, no leaks, overfills, or petroleum stained concrete were observed.

Since Tank 810 was in compliance with tank regulations and no release of JP-5 had been observed, it is recommended that no further action take place at the Tank 810 site.