

N60200.AR.003053  
NAS CECIL FIELD, FL  
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
REVIEW OF FINAL TECHNICAL MEMORANDUM FOR NO FURTHER GROUNDWATER  
MONITORING AT OPERABLE UNIT 5 (OU 5) SITE 15 NAS CECIL FIELD FL  
8/30/2001  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Jeb Bush  
Governor

# Department of Environmental Protection

Twin Towers Building  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

David B. Struhs  
Secretary

August 30, 2001

Commanding Officer  
Mr. Mark Davidson, Code 1879  
SOUTHNAVFACENCOM  
Post Office Box 190010  
North Charleston, SC 29419-9010

RE: Technical Memorandum for No Further Groundwater Monitoring at  
OU 5, Site 15, Naval Air Station Cecil Field, Florida.

Dear Mr. Davidson:

I have completed the technical review of the Technical Memorandum for No Further Groundwater Monitoring at OU 5, Site 15, Naval Air Station Cecil Field, dated August 2001 (received August 17, 2001), prepared and submitted by Tetra Tech NUS, Inc. The report adequately documents that groundwater contamination above groundwater cleanup target levels has not been observed in the eight monitoring wells located at the site. However, the Department cannot concur with No Further Action for groundwater. While monitoring of groundwater at the site does not appear necessary, the Department will require confirmatory groundwater sampling after soil remediation has been completed. The locations of groundwater monitoring wells would need to be in areas where the highest soil contaminant concentrations were detected for the various contaminants detected at the site.

If you have any concerns regarding this letter, please contact me at (850) 488-3693.

Sincerely,  
  
David P. Grabka  
Remedial Project Manager

CC: Satish Kastury, FDEP

**"Protect, Conserve and Manage Florida's Environment and Natural Resources"**