

N00207.AR.003446
NAS JACKSONVILLE
5090.3a

LETTER SUBMITTING QUARTERLY GROUNDWATER MONITORING RESULTS AND
REQUEST FOR NO FURTHER ACTION AT HANGAR 115 NAS JACKSONVILLE FL
1/20/1998
NAVFAC SOUTHERN



DEPARTMENT OF THE NAVY

NAVAL AIR STATION
JACKSONVILLE, FLORIDA 32212-5000

9806-2548

IN REPLY REFER TO:

5090

Code 184A-10/7

JAN 20 1998

Mr. Jorge Caspary
Florida Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400

Dear Mr. Caspary:

CTO 138
SUBJECT: REQUEST FOR NO FURTHER ACTION, HANGAR 115, NAVAL AIR
STATION JACKSONVILLE

We are enclosing the Fourth Quarter Monitoring Letter Report for the Hangar 115 site. Since analytical results from four quarters of monitoring show petroleum compound concentrations have decreased below the State groundwater cleanup target levels, we request that you issue a Site Rehabilitation Completion Order for the site.

Analytical results show non-petroleum constituents in the groundwater at Hangar 115. We believe the contamination is associated with potential source of contamination (PSC) 45, the building 200 wash rack located south of Hangar 115. We are investigating PSC 45 under the Installation Restoration program.

Thank you for your attention to this matter. Our point of contact is Lieutenant Beth Melendez, Facilities Department, at (904) 542-2717 extension 136.

Sincerely,

KEVIN GARTLAND
Environmental Division Director
By direction of the Commanding Officer

Enclosure (1)

Copy to: w/o enclosure

→ ABB Environmental Services Inc.

Southern Division, Naval Facilities Engineering Command (Code 1842)