

N00207.AR.003519  
NAS JACKSONVILLE  
5090.3a

LETTER REGARDING U S DEPARTMENT OF INTERIOR REVIEW AND COMMENTS ON  
FINAL DRAFT REMEDIAL INVESTIGATION AT OPERABLE UNIT 2 (OU 2) NAS  
JACKSONVILLE FL  
4/7/1997  
U S DEPARTMENT OF THE INTERIOR



IN REPLY REFER TO:

United States Department of the Interior

Hal  
0276-7559

U.S. GEOLOGICAL SURVEY  
WATER RESOURCES DIVISION  
227 N. BRONOUGH STREET, SUITE 3015  
TALLAHASSEE, FLORIDA 32301

April 7, 1997

U.S. Department of the Navy  
Commanding Officer  
Southern Division Naval Facilities Engineering Command  
Post Office Box 190010  
Charleston, South Carolina 29419-9010

Attention: Code 18511 - Mr. Anthony Robinson

Dear Sir:

Enclosed are my comments concerning the final draft Remedial Investigation Report, Operable Unit 2, Naval Air Station Jacksonville, Florida, Contract No. N62467-89-D-0317/076. Only the subjects in which the U.S. Geological Survey has expertise were reviewed, these were the sections concerning the geology and hydrology of Operable Unit 2. Specifically, the sections reviewed were 3.0 (all), 4.0 (all), 6.1, 6.2, 7.1, 7.2, and 7.5, in addition appendices G and I were reviewed.

COMMENTS:

Section 3.5: Second bullet - the thickness of the Hawthorn is about 300 (based on the Floridan well at Timuquana County Club) not more than 300 feet.

Section 4.3.2.5: Second paragraph, first sentence - the model contains 290 columns, not 2,990.

If you have any questions please do not hesitate to call me at (904) 942 9500 Ext. 3038.

Sincerely,  
For the District Chief

Hal Davis  
Hydrologist