



STATE OF TENNESSEE  
DEPARTMENT OF ENVIRONMENT AND CONSERVATION  
Division of Solid Waste Management  
Fifth Floor, L & C Tower  
401 Church Street  
Nashville, Tennessee 37243-1535

RETURN RECEIPT REQUESTED  
7003 0390 0006 6038 8269

June 21, 2005

Bill Hill  
Naval Facilities Engineering Command  
NAVFAC EFD South - OPT1  
P.O. Box 190010, 2155 Eagle Drive  
North Charleston, SC 29419-9010

Re: Technical Memorandum  
Solid Waste Management Unit (SWMU) 2 - Surface Container Removal Report  
Naval Support Activity Mid-South, Millington, TN  
Tennessee Hazardous Waste Permit Number: TNHW-094  
EPA I.D. Number: TN2 17 002 2600

Dear Sir:

The Division of Solid Waste Management (Division) has reviewed the Technical Memorandum prepared by EnSafe Inc. The report documents the surface container removal activities at SWMU 2, the former Southside landfill at Naval Support Activity Mid-South. Containers were located and documented in a previous investigation. Three 55-gallon drums were found to contain approximately 5 gallons each of a dry, soil/sludge mixture of various colors with a petroleum odor. Field personnel speculated that the material was paint-related waste. The contents of the drums were sampled and determined to be hazardous waste. The drums were picked up by a hazardous waste transporter and shipped to a disposal facility in Kentucky. The remaining containers were transported to a permitted construction debris landfill for disposal. The report recommends no further action at SWMU 2 with regard to the surface storage containers. The Division approves the recommendations contained in the report.

If there are any questions or comments regarding this review, please contact Roger Donovan at (615) 532-0864 or e-mail at [roger.donovan@state.tn.us](mailto:roger.donovan@state.tn.us).

Sincerely,

A handwritten signature in black ink, appearing to read "Roger Donovan", written over a circular stamp or mark.

Roger Donovan, P.G.  
Corrective Action Section

cc: Jennifer Herndon, EPA, Region 4, Federal Facilities Branch  
John Stedman, EnSafe  
William Krispin, Manager, Permitting Section,  
Charlie Burroughs, Manager, Corrective Action Section  
Philip Davis, Manager, Memphis EAC  
HWPU File 56 CADOTS #2005620IM-609