

N65928.AR.000567
NTC ORLANDO
5090.3a

LETTER REGARDING REGULATORY REVIEW AND APPROVAL OF OIL WATER
SEPARATOR ASSESSMENT REPORT FOR BUILDING 7184 NTC ORLANDO FL
12/13/1996
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

Department of Environmental Protection

Lawton Chiles
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Virginia B. Wetherell
Secretary

December 13, 1996

Mr. Nick Ugolini
Code 184(PVC)
Southern Division
Naval Facilities Engineering Command
2155 Eagle Drive
P.O. Box 190010
North Charleston, South Carolina 29419-9010


RE: Oil Water Separator Assessment Report, Building 7184, Naval
Training Center, Orlando, Florida

Dear Mr. Ugolini:

I have completed the technical review of the above referenced document dated October 25, 1996 (received October 29, 1996). I do not agree with the conclusions and recommendations that no further assessment is needed for the Oil/Water Separator at Building 7184. Tetrachloroethene (PCE) was previously detected in the temporary monitoring well TW-2, but was non-detect in the sampling of the newly installed permanent monitoring well MW-1. I recommend resampling MW-1 to sufficiently confirm whether PCE exists at this site. Also, I had no way of determining the groundwater flow direction as the water elevations in the measured wells was not provided either in a table or in Figure 2.

If I can be of any further assistance with this matter, please contact me at (904) 921-9989.

Sincerely,


John W. Mitchell
Remedial Project Manager

cc: Wayne Hansel, Navy SouthDiv
John Kaiser, ABB Orlando
Mac McNeil, Bechtel
Nancy Rodriguez, USEPA Region 4
Lt. Gary Whipple, NTC Orlando
Steve McCoy, Brown and Root, Oak Ridge
Bill Bostwick, FDEP Central District

TJB 

JJC 

ESN 