

N65928.AR.000569
NTC ORLANDO
5090.3a

LETTER REGARDING REGULATORY REVIEW AND NO FURTHER ACTION APPROVAL
FOR OIL WATER SEPARATOR ASSESSMENT AT BUILDING 200 NTC ORLANDO FL
12/16/1996
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

Department of Environmental Protection

Lawton Chiles
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Virginia B. Wetherell
Secretary

December 16, 1996

Mr. Nick Ugolini
Code 184 (PVC)
Southern Division
Naval Facilities Engineering Command
2155 Eagle Drive
P.O. Box 190010
North Charleston, South Carolina 29419-9010


RE: Oil Water Separator Assessment Report, Building 200, Naval
Training Center, Orlando, Florida

Dear Mr. Ugolini:

I have completed the technical review of the above referenced document dated November 1996 (received November 12, 1996). I agree with the conclusions and recommendations that a contamination assessment is needed for the eastern Oil/Water Separator. However, the information for determining groundwater flow was not in this closure assessment report. I question the groundwater flow direction as southerly due to other investigations performed in this area which indicate groundwater flow to the northeast or east-northeast. This needs to be adequately documented in the Contamination Assessment Report.

If I can be of any further assistance with this matter, please contact me at (904) 921-9989.

Sincerely,



John W. Mitchell
Remedial Project Manager

cc: Wayne Hansel, Navy SouthDiv
John Kaiser, ABB Orlando
Mac McNeil, Bechtel
Nancy Rodriguez, USEPA Region 4
Lt. Gary Whipple, NTC Orlando
Steve McCoy, Brown and Root, Oak Ridge
Bill Bostwick, FDEP Central District

TJB B

JJC JJC

ESN ESN