

N65928.AR.000604
NTC ORLANDO
5090.3a

LETTER REGARDING REGULATORY CONCURRENCE ON UNDERGROUND STORAGE
TANK PROGRAM AT STUDY AREA 3 NTC ORLANDO FL
3/10/1997
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Department of Environmental Protection

09.01.03.0011

00298

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Virginia B. Wetherell
Secretary

March 10, 1997

Mr. Wayne Hansel
Code 18B7
Southern Division
Naval Facilities Engineering Command
P.O. Box 190010
North Charleston, South Carolina 29419-0068


RE: UST Program Review and Recommendations for Petroleum
Detections in Study Area (SA) 3, NTC Orlando.

Dear Mr. Hansel:

I have completed the review of the above referenced document dated February 13, 1997 (received February 17, 1997) and concur with the conclusions and recommendations that continued monitoring of the groundwater at SA 3 continue based on contamination of petroleum constituents in monitoring well OLD-03-01. Although PCE was not detected in any of the monitoring wells from the recent round of sampling, chlorinated solvents still need to be analyzed for along with the petroleum constituents. Monitoring well OLD-03-04 should also be monitored along with OLD-03-01.

If I can be of any further assistance with this matter, please contact me at (904) 921-9989.

Sincerely,



John W. Mitchell
Remedial Project Manager

cc: Lt. Gary Whipple, NTC Orlando
Barbara Nwokike, Navy SouthDiv
Oscar "Mac" McNeil, Bechtel
Nancy Rodriguez, USEPA Region 4
Bill Bostwick, FDEP Central District
John Kaiser, ABB, Orlando
Steve McCoy, Brown & Root, Oak Ridge
Patricia Kingcade, OGC/Trustee File

TJB



JJC



ESN

