



Department of Environmental Protection

Jeb Bush
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

David B. Struhs
Secretary

April 13, 2001

Mr. Bill Hill
Code 1851
Southern Division
Naval Facilities Engineering Command
2155 Eagle Drive
P.O. Box 190010
North Charleston, South Carolina 29419-9010

RE: Site Characterization Report Addendum, Site 102,
Outlying Landing Field Bronson, Pensacola, Florida

Dear Mr. Hill:

I have completed the technical review of the above referenced document dated March 5, 2001 (received March 6, 2001). Based on my review of the data and a discussion with the Partnering Team on February 27 and 28, 2001, aluminum and iron detected in the two groundwater samples are apparently attributed to a clayey soil mound constructed at the site.

Aluminum and iron exceed their respective secondary drinking water standards only within the area adjacent to the clayey soil mound. Since the site was never used for its intended purpose and aluminum and iron do not exceed any health based GCTLs, I concur with the recommendation for no further action (NFA) at Site 102.

If I can be of any further assistance with this matter, please contact me at (850) 921-9989.

Sincerely,

Joseph F. Fugitt, P.G.
Remedial Project Manager

"Protect, Conserve and Manage Florida's Environment and Natural Resources"

Mr. Bill Hill
Page Two
April 13, 2001

cc: Ron Joyner, NAS Pensacola
Gena Townsend, USEPA Region IV
Terry Hansen, Tetra Tech NUS, Inc., Tallahassee
Charlie Goddard, FDEP Northwest District

TJB B

JJC JJC

ESN ESN