

N40003.AR.002297
PUERTO RICO NS
5090.3a

LETTER DISCUSSING POSSIBLE POLYCHLORINATED BIPHENYL CONTAMINATION AT
SITE 15 ALONG VALLEY FORGE ROAD NAVAL ACTIVITY PUERTO RICO
8/19/1994
NAVFAC MID ATLANTIC

Facsimile Cover Sheet

To: Francisco Cortez/Ivan
Rosadso
Company: RIOCC-PRA
Phone: (809) 865-2050
Fax: (809) 865-2018

From: Jim Szykman
Company: LANTDIV Code 1823
Phone: (804) 322-4795
Fax:

Date: 8/19/94

**Pages including this
cover page:** 1

Comments:

Francisco,

I talked with Rob MacPherson and Bill Deininger of M & E concerning the telephone cable to be placed through site 15. The only area that may be contaminated with PCBs is the area along Valley Forge Road as the cable comes out of the manhole (in front of bldg 90). Because of this, we suggest the cable be rerouted toward Valley Forge Road immediately after exiting the manhole and be placed about 2-3 feet from Valley Forge Road. I told this to Floref. Floref said he would pass the information on to the person in your office in-charge of the contract.

I will be out of the office on Monday and Tuesday of next week, so if you have any additional questions/concerns I suggest you talk with either Madeline Rivera or Sindulfo Castillo at Public Works Environmental.

Thanks,

Jim Szykman