

N60508.AR.000161
NAS WHITING FIELD
5090.3a

LETTER REGARDING NAVFAC SOUTHERN QUESTIONS FOR GEOTECHNICAL
PROPOSAL ABOUT NAS WHITING FIELD FL
3/14/2006
NAVFAC SOUTHERN

Newman, Katie

From: Reed, Sarah M CIV EFDSOUTH [sarah.reed@navy.mil]
Sent: Tuesday, March 14, 2006 9:30 AM
To: Smith, Larry
Subject: FW: Whiting Field IR Data
Attachments: site_status_8.5X11.pdf; site-30-south-field.pdf; Whiting_Field_IR.pdf

Hey Larry,

Please see email below. Do you know anything about Site 30?

Let me know.

-----Original Message-----

From: Callow, Beth M CIV NAVFAC WASHINGTON
Sent: Tuesday, March 14, 2006 8:26
To: Reed, Sarah M CIV EFDSOUTH
Cc: Grove, Kevin B CIV EFDSOUTH
Subject: FW: Whiting Field IR Data

Sarah,

Scott referred me to you for Whiting Field IR data. I have attached 3 documents. The first document references the site location for Site 30 South Field Maintenance Hangar. The second is the Site 30 estimated areas of impact and the remedy plan. This document was attached to a 1391 so I can't tell which document it was pulled from (maybe you can help me with the document source). The final document locates the proposed ATCT site location.

My question is what is the difference between the landuse control boundary and the site boundary. I am working on a site plan to locate an air traffic control tower (ATCT) approximately 38 feet east from the existing tower, which is located on the southeast corner of Hangar 1406. As a result the site location lies within the IR site boundary. Will I need to document this as a potential environmental hazard and ensure that proper measures are taken for soil removal? (I have already begun to do that, but I'm looking for confirmation). The hazard appears to be petroleum hydrocarbon.

Also, any ideas if those underground storage tanks really exist and if so what could be in them. I was out at the site last week and I couldn't identify any indication on the surface of the air field that they existed, but that doesn't mean they don't.

Anyhow, I would appreciate any assistance you could provide me. Thanks, Beth

<<site_status_8.5X11.pdf>> <<site-30-south-field.pdf>> <<Whiting_Field_IR.pdf>>

-----Original Message-----

From: Glass, Scott A CIV EFDSOUTH
Sent: Monday, March 13, 2006 16:33
To: Callow, Beth M CIV NAVFAC WASHINGTON
Cc: Reed, Sarah M CIV EFDSOUTH; Drawdy, William A CIV EFDSOUTH
Subject: RE: Whiting Field IR Data

Beth,

6/26/2007

Sarah Reed is our Installation Restoration Remedial Project Manager for Whiting Field, so she should be able to help you w/IR info. If you have any questions regarding the INRMP, Billy Drawdy, our Natural Resources Branch Head should be able to help you. Let me know if you need anything else.

Scott

-----Original Message-----

From: Callow, Beth M CIV NAVFAC WASHINGTON
Sent: Monday, March 13, 2006 14:16
To: Glass, Scott A CIV EFDSOUTH
Subject: Whiting Field IR Data

Scott,

I need some assistance. I am looking for IR and CERCLA data for Whiting Field. Specifically Site 30 South Field Maintenance Hangar as identified in the INRMP. Can you provide me a contact or some direction on where to look for the information.

R/

Beth M. Callow
Landscape Architect
Architectural Branch, EFDSOUTH
(843).820.5537 COMM / 583.5537 DSN