

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
LOS ANGELES REGION

101 CENTRE PLAZA DRIVE
MONTEREY PARK, CA 91754-2156
(213) 266-7500
FAX: (213) 266-7600



October 31, 1996

Mr. Duane Rollefson
Southwest Division
Naval Facilities Engineering Command
Code 1832.SR
1220 Pacific Highway
San Diego, CA 92132-5183

**BUILDING 32 SECOND QUARTER GROUNDWATER MONITORING REPORT, FORMER
NAVAL STATION LONG BEACH, CALIFORNIA (FILE NO. 90-76)**

We have received and reviewed the Navy's Building 32 Second Quarter Groundwater Monitoring Report, dated September 06, 1996. A maximum concentration of 0.60 mg/L of total petroleum hydrocarbons, as diesel, were detected in the groundwater during this sampling event. Also, the concentrations of petroleum hydrocarbons detected in the groundwater indicate a decreasing trend. Based on the above, we will require no further action for the groundwater at Building 32.

If you have any questions or comments regarding the above, please contact Hugh Marley at (213) 266-7669.


J.E. ROSS, Unit Chief
Site Cleanup Unit

cc: Alvaro Gutterez, Department of Toxic Substances Control
CDR Kevin Barre, Naval Station Long Beach
Faiq Aljabi, Navy Southwest Division, San Diego
Martin Hausladen, U.S. Environmental Protection Agency
Alan Lee, Navy Southwest Division, San Diego
Ms. Anna Ulaszewski, Naval Shipyard long Beach