

N00174.AR.001269
NSWC INDIAN HEAD
5090.3a

LETTER AND MARYLAND DEPARTMENT OF THE ENVIRONMENT COMMENTS ON THE
DRAFT FINAL SAMPLING AND ANALYSIS PLAN SUPPLEMENTAL SITE INSPECTION
GROUNDWATER SAMPLING STUMP NECK ANNEX SITES UNEXPLODED ORDNANCE 15
AND 25 (UXO 15 AND UXO 25) NSWC INDIAN HEAD MD

05/02/2014

MARYLAND DEPARTMENT OF THE ENVIRONMENT



MARYLAND DEPARTMENT OF THE ENVIRONMENT

1800 Washington Boulevard • Baltimore MD 21230

410-537-3000 • 1-800-633-6101 • www.mde.maryland.gov

Martin O'Malley
Governor

Robert M. Summers, Ph.D.
Secretary

Anthony G. Brown
Lieutenant Governor

May 2, 2014

Mr. Joseph Rail, P.E.
NAVFAC Washington
Washington Navy Yard, Bld. 212
1314 Harwood Street SE
Washington, DC 20374-5018

Re: Draft Final Sampling and Analysis Plan Supplemental Site Inspection Groundwater Sampling, Naval Support Facility Indian Head Stump Neck Annex, Sites UXO 15 and UXO 25 – September 2013

Dear Mr. Rail:

The Federal Facilities Division (FFD) of the Maryland Department of the Environment's Land Restoration Program has finished its review of the above referenced document. This document was subjected to an on-board review during the December 2013 Indian Head Installation Restoration Team meeting. In addition to the comments provided during this meeting, the FFD offers the following two comments.

1. SAP Worksheet #1
Please remove the signature block for the Maryland Department of the Environment.
2. Page 40, Section 10.4.1, first sentence on page
This sentence directs the reader to Figure 7 to view the areas and depths of soil recommended for removal. However, Figure 7 is actually an exposure pathway analysis.

If you have any questions, please contact me at (410) 537-3791.

Sincerely,

Curtis DeTore
Geological Supervisor
Federal Facilities Division

CD:cd

cc: Mr. John Burchette
Mr. Horacio Tablada
Mr. James Carroll