

N00101.AR.002432
NAS SOUTH WEYMOUTH
5090.3a

EMAIL AND COMMENTS FROM MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL
PROTECTION REGARDING DRAFT INTERIM REMEDIAL ACTION COMPLETION REPORT
FOR AREA OF CONCERN 55C NAS SOUTH WEYMOUTH MA
11/08/2010
MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL PROTECTION

Helland, Brian J CIV NAVFAC Midlant

From: Chaffin, David (DEP) [David.Chaffin@state.ma.us]
Sent: Monday, November 08, 2010 3:47 PM
To: Helland, Brian J CIV NAVFAC Midlant; Barney, David A CIV OASN (EI&E), BRAC PMO NE; Kenyon, Ronald
Cc: Keckler.Kymberlee@epamail.epa.gov
Subject: AOC 55C: Interim Remedial Action Completion Report

For Use In Intra-Agency Policy Deliberations _____

Comments on the draft Interim Remedial Action Completion Report for AOC 55C, received October 29, 2010:

1. Section 3.3: The report should include a description and discussion of the soil berm that was constructed to isolate the vernal pool area from the excavation area.
2. Section 3.3: The report should include a description of any metal debris that was recovered and disposed of separately from the contaminated soil that was removed.
3. Section 4.6: The report should explain why the northwestern "deep excavation" was not sampled.
4. Section 5.0: A document providing the wetland monitoring protocol (including invasive species control measures) should be submitted and implemented in accordance with Appendix E of the Removal Action Work Plan.
5. Table 9: The sampling date in the heading should be confirmed or corrected.
6. Figure 4 should be modified to include: (1) a label for confirmation sample PER-102, (2) a more accurate representation of the berm (e.g., the berm is not continuous), and (3) a note to explain why the northwestern "deep excavation" was not sampled.
7. The revised report should include Appendix G (post-construction professional survey, refer to p. 3-5).
8. Silt and snow fencing should be removed from the site after surface conditions have stabilized.

David Chaffin
Mass. Department of Environmental Protection One Winter Street Boston, MA 02108
Phone: 617-348-4005
FAX: 617-292-5530