

N60200.AR.003276
NAS CECIL FIELD, FL
5090.3a

LETTER REGARDING U S EPA REGION IV COMMENTS ON DRAFT TECHNICAL
MEMORANDUM FOR NO FURTHER ACTION AT POTENTIAL SOURCE OF
CONTAMINATION 39 FLIGHT LINE OUTFALLS NAS CECIL FIELD FL

3/26/2002

U S EPA REGION IV

CTO 78 0039
PSC 39
Tech Memo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 4

61 Forsyth Street, SW
Atlanta, Georgia 30303

March 26, 2002

4WD/FFB

Commander Department of the Navy
SOUTHNAVFACENGCOM
Attn: Mark Davidson
Mail Code ES339
P.O. Box 190010
North Charleston, South Carolina 29419-9010

Subject: Draft Technical Memorandum for No Further Action, dated November 2001,
Potential Source of Contamination 39 - Flightline Outfalls,
Naval Air Station Cecil Field, Jacksonville, Florida

Dear Mr. Davidson:

The U.S. Environmental Protection Agency (EPA) has reviewed the subject document and offers the following comments:

1. Section 3, page 3-1: The text is confusing and should be revised to say that 12 surface water and 14 sediment samples were collected from 14 outfalls.
2. Section 6, page 6-10 and page 6-13: The references to Outfalls 12 and 13 are incorrect and should be changed to Outfalls 13 and 14.

Should you have any questions, or if I may be of further assistance, please contact me by phone at (404) 562-8575 or by email at taylor.dawn@epa.gov.

Sincerely,

A handwritten signature in cursive script that reads "Dawn C. Taylor".
Dawn C. Taylor
Remedial Project Manager

cc: Scott Glass, SOUTHDIV
Mark Speranza, TTNUS
David Grabka, FDEP