

N61165.AR.005383  
CNC CHARLESTON  
5090.3a

LETTER REGARDING SOUTH CAROLINA DEPARTMENT OF HEALTH AND  
ENVIRONMENTAL CONTROL REVIEW OF CORRECTIVE ACTION PLAN (CAP) ADDENDUM  
RECEIVED 27 SEPTEMBER 2002 FOR ZONE C SITE 30 NH-46 CNC CHARLESTON SC  
10/03/2002  
SOUTH CAROLINA DEPARTMENT OF HEALTH AND ENVIRONMENTAL CONTROL



3 October 2002

2600 Bull Street  
Columbia, SC 29201-1708

COMMISSIONER:  
C. Earl Hunter

BOARD:  
Bradford W. Wyche  
Chairman

Mark B. Kent  
Vice Chairman

Howard L. Brilliant, MD  
Secretary

Carl L. Brazell

Louisiana W. Wright

L. Michael Blackmon

Lawrence R. Chewing, Jr., DMD

Commander  
NAVFACENCOM Southern Division  
Attn: Code ES24 (Gabriel Magwood)  
P.O. Box 190010  
North Charleston, SC 29419-9010

Re: Zone C, Site 30 Building NH 46  
**Site Identification # 01206**  
Corrective Action Plan Addendum received 27 September 2002  
Charleston County

Dear Mr. Magwood:

The Department has completed technical review of the referenced document. As submitted, the Corrective Action Plan (CAP) Addendum provides an outline of active corrective action activities designed to remediate hydrocarbon contamination at the referenced facility.

The CAP Addendum provides for the injection of Oxygen Releasing Compounds (ORC) into the subsurface to enhance remediation efforts. As stated in the request, a UIC Permit will be required for these activities, please contact Todd Adams at (803) 898-3549 or [adamst@dhc.state.sc.us](mailto:adamst@dhc.state.sc.us) to discuss permitting requirements and approvals. The CAP Addendum also notes that additional monitoring wells are not anticipated at this time, if wells do become necessary the Navy must obtain a well permit from the Department prior to installation.

The request to initiate corrective action activities as outlined in the reference document is approved for implementation with consideration for the limitations discussed above (i.e. do not proceed until you have obtained the required UIC Permit).

The baseline sampling report should be submitted to the Department no later than 31 December 2002. Should you have any questions, please contact me at 803-898-3553 (office phone), 803-898-2893 (fax) or [bishopma@dhc.state.sc.us](mailto:bishopma@dhc.state.sc.us).

Sincerely,

Michael Bishop, Hydrogeologist  
Groundwater Quality Section  
Bureau of Water

cc: Trident District EQC  
Jerry Stamps, BLWM  
Todd Adams, BOW  
Brian Crawford, 1849 Ave. F, N. Charleston SC, 29405  
Technical File