

N61165.AR.005515  
CNC CHARLESTON  
5090.3a

LETTER REGARDING SOUTH CAROLINA DEPARTMENT OF HEALTH AND  
ENVIRONMENTAL CONTROL REVIEW OF RELEASE REPORT RECEIVED DECEMBER  
2002 FOR BUILDING 1174 CNC CHARLESTON SC  
02/03/2003  
SOUTH CAROLINA DEPARTMENT OF HEALTH AND ENVIRONMENTAL CONTROL



3 February 2003

2600 Bull Street  
Columbia, SC 29201-1708

Commander  
NAVFACENGCOM Southern Division  
Attn: Code ES24 (Gabriel Magwood)  
P.O. Box 190010  
North Charleston, SC 29419-9010

COMMISSIONER:  
C. Earl Hunter

BOARD:  
Bradford W. Wyche  
Chairman

Mark B. Kent  
Vice Chairman

Howard L. Brilliant, MD  
Secretary

Carl L. Brazell

Louisiana W. Wright

L. Michael Blackmon

Larry R. Chewning, Jr., DMD

Re: CNB - BLDG 1174  
**Site Identification # 02238**  
Release Report received December 2002  
Charleston County

Dear Mr. Magwood:

Summary data for this site included in the Phase IV FOST indicated that the Navy reported a fuel oil leak that saturated the ground on 3 September 1993. The reported release is a violation of the PCA and should be investigated.

The Department requests that the Navy submit a work plan for additional assessment activities at BLDG 1174. The assessment plan should propose proper sampling of the site for petroleum hydrocarbon contamination as outlined in the South Carolina Risk-Based Corrective Action for Petroleum Releases guidance document dated May 2001.

Please submit the requested assessment plan no later than 30 May 2003. Should you have any questions please contact me at (803) 898-3553 (office phone), (803) 898-2893 (fax) or by e-mail [bishopma@dhec.sc.gov](mailto:bishopma@dhec.sc.gov). Please reference Site ID # 02238 on all future correspondence.

Sincerely,

Michael A. Bishop, Hydrogeologist  
Groundwater Quality Section  
Bureau of Water

cc: Trident District EQC  
Brian Crawford, 1849 Ave. F, N. Charleston SC, 29405  
Jerry Stamps, SCDHEC-BLWM  
Technical File