

N60201.AR.000749
NS MAYPORT
5090.3a

LETTER AND COMMENTS FROM FLORIDA DEPARTMENT OF ENVIRONMENTAL
PROTECTION REGARDING SOIL CHARACTERIZATION AND EXCAVATION MONITORING
PLAN FOR TANK SITE 283 NS MAYPORT FL

9/8/2004

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Department of Environmental Protection

Jeb Bush
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Colleen M. Castille
Secretary

September 8, 2004

Ms. Beverly Washington
Department of the Navy, Southern Division
Naval Facilities Engineering Command
2155 Eagle Drive, PO Box 190010
North Charleston, SC 29419-9010

file: 283soilExc1.doc

RE: Soil Characterization and Excavation Monitoring Plan for Tank Site 283, Naval Station
Mayport, Mayport, Florida

Dear Ms. Washington:

I have reviewed the above document dated July 2004 (received July 12, 2004). The document describes excavation and post-excavation monitoring activities; this is technically a Remedial Action Plan and will be reviewed by our engineer, Mr. Jeff Lockwood. Prior to that, please address the following in the final document:

1. Please specify that the post-excavation report and subsequent monitoring plan shall have proper professional certification.
2. It appears that the site is not fully characterized on the east side (see SB 44) for residential scenario exposure. Do you plan to place a land use control on the site?

Thank you for the opportunity to review this document. If you require further clarification or other assistance, please contact me at 850-245-8999.

Sincerely,

James H. Cason, P.G.
Remedial Program Manager

CC: Diane Lancaster, NAVSTA Mayport
Mark Peterson, TetraTech, Jacksonville
Tim Bahr, FDEP, Tallahassee

ESN ESN JJC