


N65928.AR.001205
NTC ORLANDO
5090.3a

LETTER REGARDING REGULATORY REVIEW AND COMMENTS ON SITE ASSESSMENT
FOR UNDERGROUND STORAGE TANK 2080 NTC ORLANDO FL
8/21/2001
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Department of Environmental Protection

Jeb Bush
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

David B. Struhs
Secretary

09.01.00.0027
00645

August 21, 2001

Mr. Nick Ugolini
Code 1843 (UST RPM)
Southern Division
Naval Facilities Engineering Command
P.O. Box 190010
North Charleston, South Carolina 29419-9010

RE: Site Assessment Report for UST 2080, Orlando Naval Training Center, Orlando, Florida

Dear Mr. Ugolini:

I have completed the review of the Site Assessment Report for UST 2080, Main Base, Naval Training Center, Orlando, dated March 2001 (received August 16, 2001), prepared and submitted by Tetra Tech NUS, Inc. I have the following comments on the report that should be addressed in a Site Assessment Report Addendum:

- (1) The vertical extent of groundwater contamination has not been delineated. A vertical extent monitoring well should be installed near source well OLD-2080-M02 to determine if contamination has migrated vertically.
- (2) Monitoring well construction diagrams for wells OLD-2080-M03R, OLD-2080-M05, OLD-2080-M06 and OLD-2080-M07 were not provided in Appendix C.
- (3) The well construction details in Table 2-1 for monitoring well OLD-2080-M04 do not match the information on the monitoring well sheet for that well provided in Appendix C.

If I can be of any further assistance with this matter, please contact me at (850) 921-9991.

Sincerely,


David P. Grabka
Remedial Project Manager

"Protect, Conserve and Manage Florida's Environment and Natural Resources"

Printed on recycled paper.

Mr. Nick Ugolini
Building 2080
Naval Training Center, Orlando
August 21, 2001
Page two

cc: Bill Bostwick, FDEP Central District Office
Nancy Rodriguez, USEPA, Region 4
Steve McCoy, Tetra Tech NUS, Oak Ridge, TN
Steve Tsangaris, CH2M Hill, Tampa

TJB B JJC JJC ESN ESN