

N65928.AR.002751  
NTC ORLANDO  
5090.3a

LETTER REGARDING REGULATORY REVIEW AND RECOMMENDATION ON WELL  
PURGING AT BUILDING 7111 MCCOY ANNEX NTC ORLANDO FL  
6/17/1997  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

Department of  
Environmental Protection

FILE COPY

Lawton Chiles  
Governor

Twin Towers Building  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

Virginia B. Wetherell  
Secretary

June 17, 1997

*ML* C70 107  
726.08545

Mr. Nick Ugolini  
Code 184(PVC)  
Southern Division  
Naval Facilities Engineering Command  
2155 Eagle Drive  
P.O. Box 190010  
North Charleston, South Carolina 29419-9010

RE: Request to Abandon Water Supply Well, Building 7111, McCoy  
Annex, NTC Orlando

Dear Mr. Ugolini:

I have completed the technical review of the above referenced request dated June 4, 1997 (received June 9, 1997). Benzene was detected at a level (2.8 µg/L) which would require a monitoring only plan according to current 62-770 F.A.C. guidelines. I recommend purging the well an additional time to possibly remove the benzene contamination which may have been from some residuals of the product which has been removed from the well. Sampling and analysis should be for EPA method 602/8020 only, as benzene was the only constituent detected.

If I can be of any further assistance with this matter, please contact me at (904) 921-9989.

Sincerely,

*John W. Mitchell*  
John W. Mitchell  
Remedial Project Manager

cc: Wayne Hansel, Navy SouthDiv  
Lt. Gary Whipple, NTC Orlando  
Nancy Rodriguez, USEPA Region IV  
John Kaiser, ABB, Orlando  
Bob Cohose, Bechtel, Knoxville  
Steve McCoy, Brown and Root, Oak Ridge  
Bill Bostwick, FDEP Central District

cc: M. Alonso  
J. Nash

TJB

*B*

JJC

*JJC*

ESN *ESN*