

**CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
SANTA ANA REGION**

100 IOWA AVENUE, SUITE 100
...VERSIDE, CA 92507-2409
PHONE: (909) 782-4130
FAX: (909) 781-6288

M60050.001063
MCAS EL TORO
SSIC # 5090.3



September 29, 1995

Ms. Lynne Hornecker
Southwest Division
NAVFACENGCOM
1220 Pacific Highway
San Diego, Ca 92132-5183

MARINE CORPS AIR STATION EL TORO, TANK 398 SITE, FREE PRODUCT
REMOVAL SYSTEM DRAFT CONSTRUCTION/OPERATIONS PLAN ADDENDUM

Dear Ms. Hornecker:

We received the above mentioned Plan Addendum, dated August 1995 on September 8, 1995. We have the following comments:

4.0 Task 3 Scope of Work

1. The second bullet states, "Install two 6 inch diameter product wells at the tank 398 site", assume well depth of 300 feet, including 60 feet of screen". Since the depth to groundwater is approximately 205 feet why assume well depth to be 300 feet. Also, explain why the well screen length needs to be 60 feet.
2. The last paragraph on page 4-2 refers to the SOW, which SOW is being referred to?

7.0 Permits

1. The third paragraph on page 7-2 states that, " Permits from the California Department of Toxics Substances Control (DTSC) and SARWQCB would be required for storage beyond 90 days, transportation, and disposal of contaminated soil ". DTSC is the authorized state agency that issues RCRA hazardous waste management permits, including storage and transportation. The Regional Board issues Waste Discharge Requirements and National Pollutant Discharge Elimination System (NPDES) Permits.

8.0 Soil Borings

1. During the additional site characterization phase prior to installation of the two free product recovery wells, the regulatory agencies should be informed of the findings of the fieldwork.

Ms. Lynne Hornecker


2

September 29, 1995

Also, please seek regulatory agency input in selecting the locations of the two additional free product recovery wells.

If you have any questions, please call me at (909) 782-4998.

Sincerely,

A handwritten signature in cursive script that reads "Lawrence Vitale". The signature is written in dark ink and is positioned to the left of the typed name.

Lawrence Vitale
DoD Section

cc: Mr. Juan Jimenez, Military Facilities Branch, DTSC