

4 09 *HL*

09L

09C

09G

09J

09K

09W

01

012

013

016

09A

09A1

09A2

02

04

05

3 09B *D*

08

10

11

09P

20

5090
Ser 1146CL/RWQCB Response
23 SEP 1987

California Regional Water Quality Control Board
San Francisco Bay Region
Attn: Roger E. Jones
1111 Jackson Street, Room 6040
Oakland, CA 94607

Subj: WINTERIZATION PROGRAM AT EX-HUNTERS POINT NAVAL SHIPYARD, SAN FRANCISCO, CA

As requested by your September 4, 1987 letter, enclosures (1) and (2) are provided. Your letter also requested assurance that funding and other resources will be available to implement the winterization program. Since the federal fiscal year ends on September 30, funding for this program beyond that date will be contingent upon Congressional approval of the FY88 Environmental Restoration budget request. Although we expect approval, we cannot guarantee that funding will be immediately available at the start of the fiscal year.

Enclosure (1) contains a topographical map of Ex-Hunters Point Naval Shipyard (HPNS) which identifies drainage courses, including naturally occurring wet weather rivulets. Enclosure (1) also includes a storm and sanitary drain map of the inlets and outfalls at the Shipyard. During the September 15, 1987 telephone conversation between Mr. Dave Peterson from our Architectural-Engineering (A-E) contractor, Harding and Lawson Associates, and Mr. Bill Hurley of your office, it was indicated that the maps are to the scale of 1"=200'. In that conversation, Mr. Hurley stated that the scale of 1"=200' was acceptable.

Enclosure (2) is the Health and Safety Plan prepared by our A-E contractor for the Installation Restoration Program at HPNS.

After your review of enclosure (2), please contact us so the joint shoreline inspection at HPNS requested by your letter can be arranged. We believe that such an inspection is necessary in order to clearly define the soil and storm runoff sampling requirements.

If you have questions concerning this matter, the point of contact is Commander, Western Division, Naval Facilities Engineering Command (Attn: Mr. Alex E. Dong, Code 1146, (415) 877-7505).

Sincerely,

P. W. DRENNON
CAPTAIN, CEC, USN
COMMANDER

2. 114 had seen
1. 1146 *ae 9/23*
09A

5090
Ser 1146CL/RWQCB Response

Subj: WINTERIZATION PROGRAM AT EX-HUNTERS POINT NAVAL SHIPYARD, SAN FRANCISCO, CA

Encl:
(1) Maps of Ex-Hunters Point Naval Shipyard
(2) Health and Safety Plan

Copy to:(w/o encl)
U.S. Environmental Protection Agency (Mr. Nick Morgan)
Department of Health Services (Mr. Chein (ao))
COMNAVBASE San Francisco (Mr. Joe Ruzicska)

Blind copy to: 114, 098, 101
1146, 1146CL, 1146GB, 1146RS

WRITER: C. Lee/1146CL/7502
TYPIST: C. Lee/15 Sep 87/Ser 3132h
FILE: HUNTERS PT/RWQCB RESPONSE

00
09
09L
09C
09G
09J
09K
09W
01
012
013
016
09A
09A1
09A2
02
04
05
09B
08
10
11
09P
20
24
09R

ENCLOSURE 1
MAPS OF EX-HUNTERS POINT NAVAL SHIPYARD
SUBMISSION OF MAP AND HEALTH AND SAFETY
PLAN (HASP) FOR WINTERIZATION

THE ABOVE IDENTIFIED MAPS ARE NOT
AVAILABLE.

EXTENSIVE RESEARCH WAS PERFORMED BY
SOUTHWEST DIVISION TO LOCATE THESE
MAPS. THIS PAGE HAS BEEN INSERTED AS A
PLACEHOLDER AND WILL BE REPLACED
SHOULD THE MISSING ITEMS BE LOCATED.

QUESTIONS MAY BE DIRECTED TO:

DIANE C. SILVA
RECORDS MANAGEMENT SPECIALIST
SOUTHWEST DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
1220 PACIFIC HIGHWAY
SAN DIEGO, CA 92132

TELEPHONE: (619) 532-3676

N00217.000090
HUNTERS POINT
SSIC NO 5090.3

ENCLOSURE 2
HEALTH AND SAFETY PLAN

DATED 23 SEPTEMBER 1987

IS ENTERED IN THE DATABASE AND FILED AT
ADMINISTRATIVE RECORD NO. **N00217.000010**