

5090
Ser 1832.3(DS)/L5118
26 Apr 1995

From: Commanding Officer, Engineering Field Activity West, Naval Facilities Engineering Command
To: Officer In Charge, Naval Sea System Command Detachment, Radiological Affairs Support Office (Attn: Ms. Laurie Miller)

SUBJ: REQUEST FOR CLEANUP OF AREA OF CONTAMINATED ASPHALT PAVEMENT NEAR BLDG. 364 AT THE ENGINEERING FIELD ACTIVITY WEST, HUNTERS POINT ANNEX, SAN FRANCISCO, CA

Encl: (1) Diagram of contaminated asphalt area at HPA

Ref: (a) EFA WEST ltr Ser 09ER1DS/5172 dtd 15 Feb 1995
(b) NAVSEASYSCOM Det RASO ltr Ser 01/00294 dtd 30 Mar 1995

1. Reference (a) requested a revision to the scope of RASO's assistance in the removal and disposal of LLRW to include characterization of the remaining suspected LLRW at HPA. It is requested that the scope of work be revised again to include the removal of an area of asphalt pavement contaminated with Cesium-137 near building 364. Cesium-137 spill is located in Parcel D in a fenced area between two adjacent buildings 364 and 351. It is a peanut-shaped spill the size of approximately 8 X 20 feet. Coordination between AMCCOM contractor and PRC, EFA West's contractor, will be required to gain access to the fenced area. A diagram of the spill location and site condition of the asphalt area is provided as enclosure (1).

2. In response to reference (a), Chem-Nuclear's proposal to characterize LLRW was provided as reference (b). Upon review of reference (b), it was noted that Chem-Nuclear made no mention of the disposal of LLRW. Ms. Connie Conklin of U.S. Army's AMCCOM, through a telephone conversation on 24 April 1995 with Mr. Dave Song of EFA West, stated that Chem-Nuclear is assuming that most of the LLRW will be free-released. Any LLRW which cannot be free-released will be packaged for transport. AMCCOM will, then, initiate a separate contract action with an 8-A contractor to transport the LLRW to a storage facility in Hanford, Washington, for eventual disposal.

3. Funding for this project is available. It is further requested that a detailed, total cost for these projects be submitted. Please expedite this funding request as the source of funding may become unavailable after 15 May 1995. If you have any questions regarding this matter, the point of contact is Mr. Dave Song, Code 1832.3, at (415) 244-2561.


Original signed by

RICHARD POWELL
By direction

5090
Ser 1832.3(DS)/L5118
26 Apr 1995

**SUBJ: REQUEST FOR CLEANUP OF AREA OF CONTAMINATED ASPHALT
PAVEMENT NEAR BLDG. 364 AT THE ENGINEERING FIELD ACTIVITY
WEST, HUNTERS POINT ANNEX, SAN FRANCISCO, CA**

Blind copies to (w/ enclosure):
1832(RP), 62.3(MM), 1832.3(DS), 09CMN
Admin Records (3 Copies)
Chron, blue, green
Act. File: HPA (File: L5118DS.DOC) ab



* NOT TO SCALE

ENCL (1)