

DEPARTMENT OF TOXIC SUBSTANCES CONTROL

REGION 2

9 HEINZ AVE., SUITE 200
BERKELEY, CA 94710-2737

(510) 540-2122



April 4, 1995

Commander
Department of the Navy
Engineering Field Activity, West
Naval Facilities Engineering Command
Attn: Mr. Stephen Chao, Project Manager
900 Commodore Drive, Bldg. 101
San Bruno, California 94066-2402

Dear Mr. Chao:

**PHASE I SITE 14 SOUTH CORRECTIVE ACTION CONSTRUCTION
SPECIFICATIONS, MOFFETT FEDERAL AIRFIELD (FORMERLY NAVAL AIR
STATION MOFFETT FIELD)**

The Department of Toxic Substances Control (DTSC) and San Francisco Regional Water Quality Control Board (RWQCB) have reviewed the subject document. The only comment from the State is that the Navy should clarify the origin of the BTEX clean up levels as given in Section 02220 on page 02220-7. If you have any questions, please contact me at (510) 540-3830 to ensure a coordinated approach for all regulatory comments.

Sincerely,

A handwritten signature in black ink, appearing to read "C. Joseph Chou".

C. Joseph Chou
Remedial Project Manager
Base Closure Unit
Office of Military Facilities

cc: Mr. Michael Bessette
Regional Water Quality Control Board
2101 Webster Street, Suite 500
Oakland, California 94612

Mr. Michael D. Gill
U.S. Environmental Protection Agency
Region IX, Mail Stop H-9-2
75 Hawthorne Street
San Francisco, California 94105

2197



CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD


FRANCISCO BAY REGION
WEBSTER STREET, SUITE 300
OAKLAND, CA 94612
(510) 286-1255



March 27, 1995

File No. 2189.8009 (MMB)

Mr. Joseph Chou
DTSC Region 2
Office of Military Facilities
700 Heinz Avenue, Suite 200
Berkeley, California 94710-2737



**SUBJECT: RWQCB's Comments on the Site 14 South Corrective Action
Construction Specifications at Moffett Federal Airfield.**

Dear Mr. Chou:

RWQCB staff has reviewed the above referenced report and has the following brief comment.

- As we discussed on March 24, 1995, request the Navy provide documentation on the origin of the BTEX clean up levels as given in Section 3.7 on page 02220-7.

Please call me at (510) 286-1028 if you have any questions or comments.

Sincerely,

Michael M. Bessette
Remedial Project Manager