

Gates, Bill (Efdsouth)

From: Gates, Bill (Efdsouth)
Sent: Thursday, March 14, 2002 7:21 AM
To: Ramanauskas Peter (E-mail)
Cc: Brent Tom (E-mail); Basinski Ralph (E-mail); Johnston Tom (E-mail); 'cochranm@ttnus.com'
Subject: FW: DBG



CraneSWMU2SoilSed
Metals-2B.Gat...

Pete - Replies to your questions concerning DBG ground water follow. Attached is the soils metals data. Let me know if you need anything further.

Bill

> -----Original Message-----

> From: Cochran, Matthew
> Sent: Tuesday, March 12, 2002 3:52 PM
> To: Johnston, Tom
> Subject: FW: DBG

>
> Well 02-06 was not sampled as it only contained 1 foot of water and the well riser pipe was bent, which prevented a bailer passing through the well to the bottom.

>
> All water levels in the technical memorandum are from the July 11, 2001 sample round as defined in the figure titles.

>
> -----Original Message-----
> From: Ramanauskas.Peter@epamail.epa.gov
> [mailto:Ramanauskas.Peter@epamail.epa.gov]
> Sent: Tuesday, March 12, 2002 12:25 PM
> To: brent_t@crane.navy.mil; Gates, Bill (Efdsouth)
> Subject: DBG

>
>
> Gents,
>
> Was well 02-06 sampled as part of Round 1 GW sampling? This is not shown as sampled in the Tech Memo data package you sent. Table 5-8 & Figure 5-18 in the work plan identify this as a Round 1 well. What are the results?
>
> What were soil sampling results?

>
> Are the groundwater levels for the aquifers in Figures 4 & 5 from July 2001 measurements?

>
> Thanks!