

N50092.AR.000308  
JEB FORT STORY, VA  
5090.3a

LETTER CONCERNING REPORT OF SUSPECTED OR CONFIRMED UNDERGROUND  
TANK RELEASE LIGHTER AMPHIBIOUS RESUPPLY CARGO (LARC) 60 AREA AND AUTO  
CRAFT AREA FORT STORY VA

12/20/1991

COMMONWEALTH OF VIRGINIA DEPARTMENT STATE WATER CONTROL BOARD



file

# COMMONWEALTH of VIRGINIA

STATE WATER CONTROL BOARD  
2111 Hamilton Street

Richard N. Burton  
Executive Director

Post Office Box 11143  
Richmond, Virginia 23230-1143  
(804) 367-0056  
TDD (804) 367-9763

Please reply to: Tidewater Regional Office  
287 Pembroke Office Park  
Suite 310 Pembroke No. 2  
Virginia Beach, Virginia 23462-2955  
(804) 552-1840

#### BOARD MEMBERS

William T. Clements  
Henry O. Hollimon, Jr.  
Ronald M. Plotkin  
Velma M. Smith  
Patrick L. Standing  
W. Bidgood Wall, Jr.  
Robert C. Winger

December 20, 1991

Commander  
US Army Transportation Center  
(Attention: ATZF-EHE Joan Vandervort)  
Fort Eustis, Virginia 23604-5332

re: Report of suspected or confirmed Underground Tank release, Fort Story:

<u>SWCB PC#</u>	<u>Site Name/Location</u>
92-1047	Fort Story site #6, LARC Maintenance Area
92-1048	Fort Story site #7, Auto Craft Building

Dear Commander:

The State Water Control Board (SWCB) has received notification that a release of petroleum or other regulated substance has occurred from underground storage facilities at these sites. The first reports of the releases were received by this office on September 11, 1991.

Releases from underground storage tank (UST) systems are regulated under Section 62.1-44.34:8 et seq. of the Code of Virginia and SWCB Regulation VR 680-13-02, Underground Storage Tanks; Technical Standards and Corrective Action Requirements. Specific reporting and remediation requirements and procedures are presented in VR 680-13-02 and a Leaking Underground Storage Tank (LUST) Information Sheet (Enclosure 1) that summarizes the requirements of the regulation.

If the releases have not yet been confirmed, please test your UST systems and perform Site Checks, if required, within 7 days. Please report results of your confirmation investigations to this office within 24 hours.

If the releases have been confirmed, two copies of Initial Abatement Measures Reports must be submitted to this office no later than January 13, 1992. These reports are to be followed by Site Characterization Reports, which includes site, risk, and remediation assessments and, if applicable, two copies of Free Product Removal Reports. Two copies of the Site Characterization Reports must be submitted to this office no later than February 6, 1992. Items that must be addressed in these reports are listed in Sections 6.3 through 6.5 of VR 680-13-02 and are specified in the checklists included with this package (Enclosures 2 and 3). The appropriate checklist must be included with each report when it is submitted. SWCB review of the Site Characterization Reports will determine whether further actions and/or

Page 2  
December 20, 1991  
Commander


Corrective Action Plans and Permits will be required. If you are unable to submit the required reports by the deadline, you may request deadline extensions as explained in the LUST Information Sheet.

The SWCB does have a financial reimbursement program for petroleum cleanup activities conducted in accordance with Regulation VR 680-13-02. Further information on this program and an agency contact telephone number is provided on the LUST Information Sheet.

This letter and enclosures are intended to provide you with basic information you need to comply with laws and regulations pertaining to the reported releases of regulated substances at these sites.

To expedite review of these cases, please refer to the above SWCB tracking numbers in all correspondence. If you have any questions, please call Tom Madigan at (804) 552-1840.

Sincerely,



David E. Borton  
Ground Water Manager

Enclosures

cc: SWCB-OSRR/GWR  
SWCB-TRO-OE&CA