

NWS-00218-09.04-01/07/92



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION III
841 Chestnut Building
Philadelphia, Pennsylvania 19107

Office of Superfund
Robert Thomson, PE

Direct Dial (215) 597-7858
Mail Code 3HW26

Date: January 7, 1992

Ms. Brenda Norton, PE
Atlantic Division
Naval Facilities Engineering Command
Code 1822
Norfolk, Virginia 23511-6287

Re: Yorktown Naval Weapons Station, Va.
Corrections to TRC Minutes

Dear Ms. Norton:

I have reviewed the Minutes of the Technical Review Committee Meeting of December 17, 1991, and noted that the following corrections are necessary:

Page 4, 9th statement

-*"Low pH would keep metals from dissolving in groundwater."* is incorrect. It should be changed to "Low pH would tend to keep metals in solution in groundwater".

Page 4, 11th statement

-*"2,4 and 2,6 degradation products of TNT have a high slope for carcinogens."* should be modified to "2,4 and 2,6 degradation products of TNT have a steep slope for carcinogenicity."

Page 11, 11th statement

-*"How far up Felgates Creek have we found explosives, or is it in the York"* should be modified for clarity as follows; "How far up Felgates Creek have we found explosives, and have explosives been sampled for and detected in the York River?".

If you have any questions concerning this matter, please feel free to call me at the telephone number listed above,

Sincerely,

A handwritten signature in cursive script that reads "Robert Thomson".

Robert Thomson, PE
Federal Facilities (3HW26)

cc: Jennifer Loftin, WPSTN-Yorktown, Va.
Judith Delconte, Weston-West Chester, Pa.