

N60200.AR.002511
NAS CECIL FIELD, FL
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
REVIEW OF SEMI-ANNUAL/ANNUAL GROUNDWATER MONITORING REPORT FOR
BUILDING 404 TANK 404 NAS CECIL FIELD FL

7/6/2000

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Department of Environmental Protection

Jeb Bush
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

David B. Struhs
Secretary

July 6, 2000

Commanding Officer
Mr. Nick Ugolini, Code 1843
SOUTHNAVFACENGCOM
Post Office Box 190010
North Charleston, SC 29419-0068

RE: Building 404, Tank 404, Semi-Annual/Annual Groundwater
Monitoring Report, Naval Air Station Cecil Field,
Florida.

Dear Mr. Ugolini:

I have completed the technical review of the Annual
Groundwater Monitoring Report, dated June 2000 (received June 5,
2000) submitted for the above-referenced site. FDEP does not
concur with the proposed recommendation of No Further Action for
this site. A monitoring well must be installed downgradient of
CEF 404-1S and sampled using USEPA Methods 602, 8310, and FL-Pro.
Based on this data, a recommendation should be submitted for
future actions at this site.


If you have any concerns regarding this letter, please
contact me at (850) 921-9991.

Sincerely,

Michael J. Deliz, P.G.
Remedial Project Manager

6-JULY-00

Date



CC: Debbie Vaughn-Wright, USEPA - Atlanta
John Flowe, City of Jacksonville
Scott Glass, SOUTHNAVFACENGCOM
Mark Speranza, TTNUS - Pittsburgh

TJB B JJC JJL ESN ESN

"Protect, Conserve and Manage Florida's Environment and Natural Resources"