

N60200.AR.002973
NAS CECIL FIELD, FL
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
REVIEW OF SEMI-ANNUAL GROUNDWATER MONITORING REPORT FOR BUILDING 428
TANK 428 NAS CECIL FIELD FL
6/1/2001
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Department of Environmental Protection

Jeb Bush
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

David B. Struhs
Secretary

June 1, 2001

Mr. Nick Ugolini
Code 1843 (UST RPM)
Southern Division
Naval Facilities Engineering Command
Post Office Box 190010
North Charleston, South Carolina 29419-9010

RE: Semi-Annual Groundwater Monitoring Report, Building 428,
Tank 428, Naval Air Station Cecil Field, Jacksonville,
Florida

Dear Mr. Ugolini:

I have completed the review of the Semi-Annual Groundwater Monitoring Report, Building 428, Tank 428, Naval Air Station Cecil Field, dated April 6, 2001 (received April 9, 2001), prepared and submitted by Tetra Tech NUS, Inc. While the report is adequate for its intent, there is some concern that the Navy was not notified by the tenant that monitoring wells had been destroyed at the site. Because the wells were destroyed without the Navy's knowledge, the last sampling event was delayed for almost half a year. Please notify all tenants that are occupying areas where monitoring wells exist of the location of those monitoring wells and who to notify when monitoring wells are damaged or destroyed.

If I can be of any further assistance with this matter, please contact me at (850) 488-3693.

Sincerely,


David P. Grabka
Remedial Project Manager

cc: Scott Glass, Southern Division
Debbie Vaughn-Wright, USEPA Region 4
Mark Speranza, TetraTech NUS, Pittsburgh
Sam Ross, CH2M Hill Constructors, Inc.
Mike Fitzsimmons, FDEP Northeast District

TJB 

JJC 

ESN 